

Volume 8

Asbestos-Containing Material Re-inspection For Building 36 Charleston Naval Shipyard Charleston, South Carolina

Contract No. N2467-96-D-0998 Delivery Order No. 0013

Prepared for:

Department of the Navy Southern Division NAVFACENGCOM 2305 Eagle Drive North Charleston, SC 29419

Prepared by:

BAT Associates, Inc. 5151 Brook Hollow Parkway Suite 250 Norcross, Georgia 30071 (770) 242-3908

APPENDIX A SAMPLE AND ACM LOCATION DRAWINGS

APPENDIX B PHOTOGRAPHIC DOCUMENTATION OF IDENTIFIED ACM

APPENDIX C PERSONNEL AND LABORATORY ACCREDITATIONS

APPENDIX D LABORATORY ANALYSIS RESULTS

Volume 8

Asbestos-Containing Material Re-inspection For Builing 36 Charleston Neval Shipyard Charleston, South Carolina

Contract No. N2467-96-D-0998 Delivery Order No. 0013

Prepared for:

Department of the Navy Southern Division NAVFACENGCOM 2305 Eagle Drive North Charleston, SC 29419

Prepared by:

BAT Associates, Inc. 5151 Brook Hollow Parkway Suite 250 Norcross, Georgia 30071 (770) 242-3908

TABLE OF CONTENTS

		<u>Page</u>
1.0	Executive Summary	1
2.0	Building Inspection Information Form	3
3.0	Introduction	4
4.0	Sampling Methodology	5
5.0	Asbestos Inventory and Assessment	8
6.0	Summary of Sample Analysis Results	9
7.0	Results of Quality Control Sampling	10
8.0	Physical Assessment of Identified ACM	11
9.0	Hazard Assessment of Identified ACM	22
10.0	Preliminary Cost Estimate for Removal of Identified ACM	31
11.0	Conclusions	32
	Appendices	
Appendix A Appendix B Appendix C Appendix D	Sample and ACM Location Drawings Photographic Documentation of Identified ACM Personnel and Laboratory Accreditations Laboratory Analysis Results	
	List of Tables and Figures	
Table 1.0 Table 2.0 Table 3.0 Table 4.0 Table 5.0	Summary of Identified ACM Recommended Response Actions Summary of Identified Suspect ACM Summary of Sample Analysis Results Validation of Quality Control Sampling	1 2 8 9 10
Figure 1.0	Decision Tree Diagram For Hazard Assessment	23

1.0 EXECUTIVE SUMMARY

BAT Associates, Inc. (BAT) was retained by the U.S. Department of the Navy, Southern Division (SouthDiv), Naval Facilities Engineering Command (NAVFACENGCOM) to perform an asbestos-containing material (ACM) re-inspection of Building 36 located at the Charleston Naval Shipyard (CNS) in Charleston, South Carolina.

A list of ACM identified in Building 36 is summarized in Table 1.0.

Table 1.0 Summary of Identified ACM

HA No.	Material Description	Sample Analysis Results	Approx. Quantity of ACM	NESHAP Category
1	Floor Tile, 9" x 9" black w/ black mastic	Tile = 7% chrysotile, Mastic = 2% chrysotile	14,000 SF	Category I, non-friable
3	Floor Tile, 12" x 12" off-white with brown streaks w/ black mastic	Tile= 10% chrysotile, Mastic= 1-2% chrysotile	7,000 SF	Category I, non-friable
4	Floor Tile, 12" x 12" beige with gray speckles w/ black mastic	Tile = 3% chrysotile, Mastic = 5% chrysotile	7,240 SF	Category I, non-friable
5	Floor Tile, 12" x 12" lime green with white streaks w/ black mastic	Tile = 5% chrysotile, Mastic = 10% chrysotile	7,000 SF	Category I, non-friable
13	Pipe Fitting Insulation, 3" white with canvas wrap on steam	15-20% chrysotile, 15-20% amosite	300 EA	Regulated, friable
14	Pipe Fitting Insulation, 3" with canvas wrap on domestic water	Assumed to contain asbestos due to inaccessibility of the material in walls	375 EA	Regulated, friable
17	Pipe Insulation, 12" with metal wrap	Layer 1= 15% amosite, Layer 2= NAD	160 LF	Regulated, friable

NOTES:

HA = Homogeneous Area

SF = Square Feet

LF = Linear Feet

1. One percent or less asbestos content is considered a non-asbestos-containing material by EPA and the State of South Carolina.

EA = Each

- Federal and state regulations require a minimum of three non-asbestos-containing analysis results per homogeneous area (material) to classify that material as being a non-asbestos-containing material. However, one "positive" asbestos-containing analysis result would classify that material as being an asbestos-containing material.
- 3. No Quality Control discrepancies were noted.

BAT recommends the following management actions for the identified ACM in Building 36 in Table 2.0.

Table 2.0 Recommended Response Actions

HA No.	Material Description	Recommended Response Action
1	Floor Tile, 9" x 9" black w/ black mastic	Remove prior to renovation or demolition
3	Floor Tile, 12" x 12" off-white with brown streaks w/ black mastic	Remove prior to renovation or demolition
4	Floor Tile, 12" x 12" beige with gray speckles w/ black mastic	Remove prior to renovation or demolition
5	Floor Tile, 12" x 12" lime green with white streaks w/ black mastic	Remove prior to renovation or demolition
13	Pipe Fitting Insulation, 3" white with canvas wrap on steam	Remove prior to renovation or demolition
14	Pipe Fitting Insulation, 3" with canvas wrap on domestic water	Remove prior to renovation or demolition
17	Pipe Insulation, 12" with metal wrap	Remove prior to renovation or demolition

Other suspect ACM not identified could be present in areas of the building inaccessible to the asbestos building inspectors. For example, materials could exist in walls and other locations where access could only be gained by demolition of the building. Also, other materials currently not recognized by the asbestos building inspection industry could exist.

The total estimated cost for the removal of the identified and/or assumed ACM in Building 36 is approximately \$130,100. See Section 10.0 for a break down of the preliminary cost estimate for the removal of the identified or assumed ACM.

2.0 BUILDING INSPECTION INFORMATION FORM

Building Name: Barracks

Building Number: 36

Facility: Charleston Naval Shipyard

Building Area (square footage): 35,880

Year Built: 1959

Building Type: Living Quarters

No. of Floors in Building: Three

Purpose of ACM Survey: Re-Inspection

Facility Unit Identification Code

(UIC):

N/A

Building Contact: Mr. Matthew Humphrey

Contact's Telephone No.: (843) 743-9985

Building Survey Date(s): November 26, 1999 and January 28, 2000

Asbestos Inspector's Name: Mr. Jason McGlashan, and Mr. Foshie Bell

Asbestos Inspector's Accreditation No: GA2900

Inspection Company: BAT Associates, Inc.

Company Telephone No. (770) 242-3908

3.0 INTRODUCTION

BAT Associates, Inc. (BAT) was retained by the U.S. Department of the Navy, Southern Division (SouthDiv), Naval Facilities Engineering Command (NAVFACENGCOM) to perform an asbestos-containing material (ACM) re-inspection of all buildings located at the Charleston Naval Shipyard in Charleston, South Carolina. The purpose of this re-inspection was to:

- 1. Perform a comprehensive ACM re-inspection of 34 buildings in accordance with Federal and U.S. Navy requirements;
- 2. Assess the condition of previously identified friable and non-friable ACM; and
- 3. Provide a preliminary cost estimate for the removal of identified ACM.

The re-inspection was performed in accordance with the Navy's Asbestos Facility Inventory/Assessment Protocol (NEESA 70.2-010) and the U.S. Environmental Protection Agency's (USEPA) Asbestos Hazard Emergency Response Act (AHERA) and the Asbestos School Hazard Abatement Reauthorization Act (ASHARA).

The results of the re-inspection survey are presented in 24 separate volume reports. This report describes the results for Building 36.

This re-inspection survey was performed by Mr. Jason McGlashan and Mr. Foshie Bell, under the direct supervision of Mr. Douglas J. Milton, CIH, on November 26, 1999 and January 28, 2000. Mr. McGlashan is an accredited building inspector. Mr. Bell is an accredited asbestos building inspector and management planner. Mr. Milton, a Certified Industrial Hygienist, is an accredited asbestos inspector, management planner, and project designer.

This report discusses the sampling methodology used during the re-inspection and assessment (Section 4.0); a list of all identified suspect materials (Section 5.0); a summary of the bulk sample analysis results (Section 6.0); results of quality control sampling; (Section 7.0); physical assessments of the identified ACM (Section 8.0); a hazard assessment of the identified ACM (Section 9.0); preliminary cost estimates for removal (Section 10.0); and conclusions (Section 11.0). Appendix A contains drawings identifying the location of collected bulk samples and the locations of identified ACM. Appendix B contains photographic documentation of identified ACM. Appendix C contains personnel and laboratory accreditations. Appendix D contains laboratory analysis results.

The assessment protocol for ACM involved three distinct steps:

1. Performed preliminary walk-though of the building to identify suspect ACM and to determine the amount of suspect ACM, to define the number of samples to be collected, to identify access problems (e.g., collection of samples in a limited access pipe chase below the building), and to determine the degree of personal protection necessary for the bulk sample collection.

- 2. Visually inspected the building for ACM to identify the location of the suspect ACM and to determine if the material was friable or non-friable. Suspect materials were then categorized according to the EPA National Emission Standards for Hazardous Air Pollutants (NESHAP) for asbestos as: Category I non-friable materials, Category II non-friable materials, and Regulated (friable) Asbestos-Containing Materials (RACM).
- 3. Collected bulk samples for the analysis for asbestos content (see Section 4.0, *Sampling Methodology*, for details).

4.0 SAMPLE METHODOLOGY

Representative, randomly selected bulk samples were collected in accordance with the Navy's and AHERA sampling protocol, as described in 40 CFR 363.36, and in accordance with BAT's contract requirements. Bulk samples were collected from homogenous areas (materials) in a manner that minimized any release of airborne asbestos fibers. A homogeneous area (material) is defined as a material uniform in size, color and texture.

The minimum number of samples collected from each homogeneous area was as follows:

- 1. Friable Spray-Applied or Trowel-Applied Material (including plaster)
 - a. Less than or equal to 1,000 Square Feet (S.F.) = 3 samples
 - b. Greater than 1,000 S.F and less than or equal to 5,000 S.F. = 5 samples
 - c. Greater than 5,000 = 7 samples
- 2. Pipe and Duct Insulation
 - a. Three samples per homogeneous area of insulation.
- 3. Elbows, Valves, Fittings, and Connection Mud

Three representative samples from each type of insulated elbow, valve, fitting, and connection mud.

4. Boiler, Tanks, and Furnaces

A minimum of 3 samples per unit.

5. Patchwork

Patchwork is defined as a patch or repair to existing material based on the following quantities:

- a. Surfacing material patches are limited to a maximum of 6 S.F.
- b. Pipe and duct insulation patches are limited to a maximum of 6 Linear Feet (L.F.) or 6 S.F.
- c. Boiler, tank, and furnace patches are limited to 6 S.F.

If the patchwork exceeded the limits prescribed above, it was sampled according to the homogeneous area protocol in items 1 to 4 above. If a material qualifies as patchwork, a single sample was collected per patch.

6. Ceiling or Acoustical Tile

3 samples

7. Miscellaneous Friable Material

3 samples

8. Non-Friable Material

Non-friable materials for purpose of this survey included Transite-type panels, floor tiles, floor tile mastic, and other miscellaneous materials.

Minimum of 3 samples.

The procedures followed for collection of each bulk sample is outlined briefly below:

- 1. The accredited inspector collecting the sample was equipped with the appropriate personal protective equipment. This included a half-mask airpurifying respirator, protective gloves and protective eyewear.
- 2. The surface of the material being sampled was wetted with amended water (containing a surfactant to aid penetration) mist to lessen the risk of fiber release during sampling.
- 3. Each sample was extracted using the appropriate equipment, (e.g., a sample container, knife, core borer). Care was taken to insure that all layers of the suspect materials, down to the substrate, were included in the sample.
- 4. Each sample was placed in an individual container, which was then sealed and labeled with a unique identification number which was also recorded on the sample data log-in sheet.

- 5. After each sample was collected, the area immediately surrounding the sampling location was inspected for debris and wet-cleaned as necessary to lessen the risk of an airborne fiber release.
- 6. All necessary data were recorded on the BAT Suspect Material Inventory Form including sample number, sample location, type of suspect material, name of inspector collecting the sample and other relevant information.
- 7. Samples were then transported to Cape Environmental Management Inc. (CAPE) Asbestos Laboratories in Atlanta, Georgia, for Polarized Light Microscopy (PLM) analysis. The CAPE Asbestos Laboratory participates in the National Voluntary Laboratory Assurance Program (NVLAP) for the analysis of asbestos content in suspect materials. CAPE's NVLAP Laboratory Code is 102111-0.
- 8. BAT collected duplicate samples during the collection of primary bulk sampling for quality control (QC) purposes. QC samples were collected at ten percent of the bulk sample locations. They were assigned unrelated sample identification numbers and analyzed by Analytical Environmental Services, Inc. (AES). AES participates in the National Voluntary Laboratory Assurance Program (NVLAP) for the analysis of asbestos content in suspect materials. AES's NVLAP Laboratory Code is 102033-0.
- 9. Upon receipt by the laboratory, the samples were logged in and assigned a unique laboratory identification number. The laboratory analyzed the samples in accordance with 40 CFR 363.87 subpart F. Copies of the laboratory accreditations for both laboratories may be found in Appendix C.

5.0 ASBESTOS INVENTORY AND ASSESSMENT

Table 3.0 describes the suspect ACM identified in and around Building 36.

Table 3.0 Summary of Identified Suspect ACM

HA			AHERA Category
No.	Description of Suspect ACM	Location of Suspect ACM	of Material
1	Floor Tile, 9" x 9" black w/ black mastic	First floor, throughout (under HA # 4 and 5; second floor, throughout (under HA #3)	Misc.
2	Floor Tile, 9" x 9" dark blue with white streaks w/ black mastic	First floor, day room	N/A
3	Floor Tile, 12" x 12" off-white with brown streaks w/ black mastic	Second floor, throughout (over HA # 1)	Misc.
4	Floor Tile, 12" x 12" beige with gray speckles w/ black mastic	First floor, main lobby (aver HA # 1); third floor, throughout	Misc.
5	Floor Tile, 12" x 12" lime green with white streaks w/ black mastic	First floor, rooms and corridors (over HA # 1)	Misc.
6	Drywall, on walls	Throughout the building	N/A
7	Joint sealer Compound, on drywall	Throughout the building	N/A
8	Ceiling Tile, 2' x 2' white suspended groove and pinhole (new)	Second floor, center corridor	N/A
9	Ceiling Tile, 2' x 4' white suspended groove and pinhole (old)	Third floor, center corridor	N/A
10	Ceiling Tile, 2' x 4' white suspended groove and pinhole (new)	Third floor, center corridor	N/A
11	Mastic on Sink, black	Second floor, writing room	N/A
12	Window Glazing, interior	All interior windows	N/A
13	Pipe Fitting Insulation, 3" white with canvas wrap on steam	Piping on all wall mounted radiators	TSI
14	Pipe Fitting Insulation, 3" with canvas wrap on domestic water	All floors, in walls behind all water fixtures	TSI
15	Roofing, built-up	Roof	N/A
17	Pipe Insulation, 12" with metal wrap	In crawl space and between Buildings 36 and 37	TSI
18	Tank Insulation	In exterior mechanical room	N/A

Notes:

Misc. = Miscellaneous Material

N/A = Not Applicable

6.0 SUMMARY OF SAMPLE ANALYSIS RESULTS

Table 4.0 contains a summary of the bulk sample analysis results for suspect ACM identified in this building. Sample identification numbers do not necessarily match the building number since barracks 31, 32, 33, 34, 35, and 36 are of similar construction, have the same square footage, and the same construction date and were inspected as one unit.

All thermal system insulation (TSI), if present, was classified as friable material. As long as the outer covering remains intact and is in good condition the TSI can be considered non-friable (29 CFR 363.85). Ceiling tile, if asbestos is present was considered a friable material. However, if non-friable materials are drilled, sawed, ground or otherwise physically or mechanically disturbed, they may release asbestos fibers to the environment and therefore would be considered a friable material.

According to AHERA protocol, all samples within a homogeneous area must have an asbestos content of one percent or less by weight using Polarized Light Microscopy (PLM) analysis before the material can be categorized as non-asbestos-containing. If one sample is determined as asbestos-containing using PLM analysis, the entire homogeneous area must be classified asbestos-containing.

Table 4.0 Summary of Sample Analysis Results

HA	Sample	Suspect Material Description	Asbestos Content	Friability
No.	ID No.			
1	31-5-1	Floor Tile, 9" x 9" black w/ black	Tile = 7% chrysotile,	Friable
		mastic	Mastic = 2% chrysotile	
2	32-2-1, 32-2-2,	Floor Tile, 9" x 9" dark blue with	Tile = NAD,	N/A
	32-2-3	white streaks w/ black mastic	Mastic = NAD	
3	31-2-1	Floor Tile, 12" x 12" off-white with	Tile = 10% chrysotile,	Friable
		brown streaks w/ black mastic	Mastic = 1-2% chrysotile	
4	36-4-1	Floor Tile, 12" x 12" beige with	Tile = 3% chrysotile,	Friable
		gray speckles w/ black mastic	Mastic = 5% chrysotile	
5	36-5-1	Floor Tile, 12" x 12" lime green	Tile = 5% chrysotile,	Friable
		with white streaks w/ black mastic	Mastic = 10% chrysotile	
6	31-10-1, 31-10-2,	Drywall, on walls	NAD	N/A
	31-10-3			
7	31-11-1, 31-11-2,	Joint sealer Compound, on drywall	NAD	N/A
	31-11-3			
8	34-19-1, 34-19-2,	Ceiling Tile, 2' x 2' white	NAD	N/A
	34-19-3	suspended groove and pinhole (new)		
9	31-6-1, 31-6-2,	Ceiling Tile, 2' x 4' white	NAD	N/A
	31-6-3	suspended groove and pinhole (old)		
10	31-7-1, 31-7-2,	Ceiling Tile, 2' x 4' white	NAD	N/A
	31-7-3	suspended groove and pinhole (new)		/.
11	36-3-1, 36-3-2,	Mastic on Sink, black	NAD	N/A
	36-3-3			
12	36-4-1, 36-4-2,	Window Glazing, interior	NAD	N/A
12	36-4-3	D' - E''- I - I - I - I' - O'' - I'	15 20 5 1 11	
13	33-3-1, 33-3-2, 33-3-3	Pipe Fitting Insulation, 3" white	15-20% chrysotile,	Friable
1.4		with canvas wrap on steam	15-20% chrysotile	
14	Assumed	Pipe Fitting Insulation, 3" with	Assumed to contain	Friable
		canvas wrap on domestic water	asbestos due to	
			inaccessibility of material	
15	26 15 1 26 15 2	Deefing built up	in walls	27/4
15	36-15-1, 36-15-2,	Roofing, built-up	NAD	N/A
	36-15-3			

HA No.	Sample ID No.	Suspect Material Description	Asbestos Content	Friability
17	Exterior Pipe-32	Pipe Insulation, 12" with metal wrap	Layer 1 = 155 amosite, Layer 2 = NAD	Friable
18	B36-S1, B36-S2, B36-S3	Tank Insulation	NAD	N/A

Notes:

NAD = No Asbestos Detected

N/A = Not Applicable

7.0 RESULTS OF QUALITY CONTROL SAMPLING

The purpose of quality control (QC) sampling was to ensure reproducibility of the primary laboratory analysis results. Duplicate samples were collected for ten percent of the total building samples for QC purposes.

Table 5.0 Validation of Quality Control Sampling

Sample I.D. No.	Primary Laboratory Analysis Results	QC Laboratory Analysis Results
36-4-1QC	Tile = 3% chrysotile, Mastic = 5% chrysotile	Tile = 7% chrysotile, Mastic = 3% chrysotile

No discrepancies between primary laboratory and quality control laboratory bulk sample analysis were noted.

8.0 PHYSICAL ASSESSMENT OF IDENTIFIED ACM

The following sections contain a summary of the methodology BAT specialists used to conduct the physical assessment for this building. This methodology was developed in accordance with USEPA AHERA re-inspection requirements contained in 40 CFR Part 363.85.

- 1. Physical Assessment for Friable ACM.
 - A. Condition. Friable ACM were assigned to one of the following categories based on a visual inspection and touch test:
 - 1) **Significantly Damaged Condition.** Material which met one or both of the following characteristics:
 - a. Ten percent (10%) or more of the material in the functional space is crumbled, blistered, or is hanging from the surface, deteriorated, showing adhesive failure, water stained, gouged or marred, and the damage is evenly distributed.
 - b. Twenty-five percent (25%) or more of the material in the functional space is crumbled, blistered, or is hanging from the surface, deteriorated, showing adhesive failure, water stained, gouged or marred, and the damage is localized.
 - 2) **Damaged Condition.** Material which met one or both of the following characteristics:
 - a. The surface is crumbling, blistered, water stained, gouged or marred, or otherwise damaged on less than ten percent (10%) of the material in the functional space (but material is too damaged to be characterized as good condition) and the damage is evenly distributed.
 - a. The surface is crumbling, blistered, water stained, gouged or marred, or otherwise damaged on twenty-five percent (25%) or more of the material in the functional space (but material is too damaged to be characterized as good condition) and the damage is localized.
 - Good Condition. Material with very limited, or no visible damage or deterioration.
 - B. **Potential for Disturbance.** Friable ACM were assigned to one of the following categories based on a visual inspection and assessment of surroundings:

- 1) **Potential for Significant Damage.** Material which met one or more of the following conditions:
 - a. High potential for Contact. Service workers are in the vicinity of the material more than once each week <u>or</u> the material is in a public area and is accessible to building occupants.
 - b. High Potential for Vibration. Loud motors or engines present in the vicinity of the material <u>or</u> there are intrusive noises or easily sensed vibrations from surrounding area, such as nearby highways or airports.
 - c. High Potential for Air Erosion. High velocity air moving across or against material.
- 2) **Potential for Damage.** Material which met one or more of the following conditions for potential for significant damage:
 - a. Moderate Potential for Contact. Service workers are in the vicinity of the material at least once each month, but less than once each week or the material is in a room or office and is accessible to the occupants.
 - b. Moderate Potential for Vibration. Motors or engines present but not obtrusive <u>or</u> occasional loud noise in the vicinity of the material.
 - c. Moderate potential for Air Erosion. Noticeable movement of air across or against material, but not high in velocity.
- 3) Low Potential for Damage. Material which met one or more of the following conditions and met none of the conditions for potential for significant damage or potential for damage:
 - a. Low Potential for Contact. Service workers are in the vicinity of the material less than once each month or the material is visible but not accessible to the building occupants in the course of normal activity.
 - b. Low Potential for Vibration. None of the conditions for high or moderate potential for vibration are met.
 - c. Low Potential for Air Erosion. None of the conditions for high or moderate potential for air erosion are met.

- 2. Physical Assessment for Thermal ACM.
 - A. Condition. Thermal ACMs were assigned to one of the following categories based on a visual inspection:
 - 1) **Significantly Damaged Condition.** Material which met one or both of the following characteristics:
 - a. Missing jackets, crushed, heavily gouged, or punctured insulation on equal to or greater than ten percent (10%) of the material in the functional space, and the damage is evenly distributed.
 - b. Missing jackets, crushed, heavily gouged, or punctured insulation on equal to or greater than twenty-five percent (25%) of the material in the functional space, and the damage is localized.
 - 2) **Damaged Condition.** Material which met one or both of the following characteristics:
 - a. Missing jackets, crushed, heavily gouged, or punctured insulation on less than ten percent (10%) of the material in the functional space, and the damage is evenly distributed.
 - b. Missing jackets, crushed, heavily gouged, or punctured insulation on greater than twenty-five percent (25%) of the material in the functional space, and the damage is localized.
 - 3) Good Condition. Material with very limited, or no visible damage or deterioration.
 - B. **Potential for Disturbance.** Thermal ACMs were assigned to one of the following categories based on a visual inspection and assessment of surroundings:
 - 1) **Potential for Significant Damage.** Material which met one or more of the following conditions:
 - a. High Potential for Contact. Service workers are in the vicinity of the material more than once each week <u>or</u> the material is in a public area and is accessible to building occupants.
 - b. High Potential for Vibration. Loud motors or engines present in the vicinity of the material <u>or</u> there are intrusive noises or easily sensed vibrations from surrounding area, such as a nearby highway or airport.

- c. High Potential for Air Erosion. High velocity air moving across or against the material.
- 2) **Potential for Damage.** Material which met one or more of the following conditions and met none of the conditions for potential for significant damage.
 - a. Moderate Potential for Contact. Service workers are in the vicinity of the material at least once each month but less than once each week <u>or</u> the material is in a room or office and is accessible to the occupants.
 - b. Moderate Potential for Vibration. Motors or engines present but not obtrusive <u>or</u> occasional loud noise in the vicinity of the material.
 - c. Moderate Potential for Air Erosion. Noticeable movement of air across or against material, but not high in velocity.
- 3) Low Potential for Damage. Material which met one or more of the following conditions and met none of the conditions for potential for significant damage or potential for damage:
 - a. Low Potential for Contact. Service workers are in the vicinity of the material less than once per month or the material is visible but not accessible to the building occupants in the course of normal activity.
 - b. Low Potential for Vibration. None of the conditions for high or moderate potential for vibration are met.
 - c. Low Potential for Air Erosion. None of the conditions for high or moderate potential for air erosion are met.

BUILDING: Charleston Naval Shipyard, Building Number 36

SAMPLE NUMBER(S): 31-5-1

HOMOGENEOUS AREA No.: 1

TYPE OF MATERIAL:

Surfacing

TSI

X Other

Description: Floor Tile, 9" x 9" black w/ black mastic

Approximate Amount of Asbestos-Containing Material (Linear or Square Foot): 14,000 SF

CONDITION:

Percent Damage:

≤1 % Damage

Localized

Distributed

Type of Damage:

Deterioration

Water

Physical

DESCRIPTION:

Overall Rating:

Good

Fair

Poor

POTENTIAL FOR DISTURBANCE:

Frequency of Potential Contact:

X High

Moderate

Low

Description: Material is located in high traffic areas.

Influence of Vibration:

High

Moderate

X Low

Description:

None identified.

Potential for Air Erosion:

High

Moderate

X Low

Description:

None identified.

OVERALL RATING:

 $\underline{\mathbf{X}}$ Potential for

Potential for

Low Potential for

Significant Damage

Damage

Damage

COMMENTS:

Material should be removed prior to renovation or demolition.

BAT Associates, Inc.

15

BUILDING: Charleston Naval Shipyard, Building Number 36

SAMPLE NUMBER(S): 31-2-1

HOMOGENEOUS AREA No.: 2

TYPE OF MATERIAL:

Surfacing

TSI

X Other

Description: Floor Tile, 12" x 12" off-white with brown streaks w/ black mastic

Approximate Amount of Asbestos-Containing Material (Linear or Square Foot): 7,000 SF

CONDITION:

Percent Damage:

<1 % Damage

Localized

Distributed

Type of Damage:

Deterioration

Water

Physical

DESCRIPTION:

Overall Rating:

Good

Fair

Poor

POTENTIAL FOR DISTURBANCE:

Frequency of Potential Contact:

X High

Moderate

Low

Description: Material is located in high traffic areas.

Influence of Vibration:

High

Moderate

X Low

Description:

None identified.

Potential for Air Erosion:

High

Moderate

X Low

Description:

None identified.

OVERALL RATING:

 \underline{X} Potential for

Potential for

Low Potential for

Significant Damage

Damage

Damage

COMMENTS:

Material should be removed prior to renovation or demolition.

BAT Associates, Inc.

16

BUILDING: Charleston Naval Shipyard, Building Number 36

SAMPLE NUMBER(S): 36-4-1

HOMOGENEOUS AREA No.: 4

TYPE OF MATERIAL:

Surfacing

TSI

X Other

Description: Floor Tile, 9" x 9" beige with gray speckles w/ black mastic

Approximate Amount of Asbestos-Containing Material (Linear or Square Foot): 7,240 SF

CONDITION:

Percent Damage:

<1 % Damage

Localized

Distributed

Type of Damage:

Deterioration

Water

Physical

DESCRIPTION:

Overall Rating:

Good

Fair

Poor

POTENTIAL FOR DISTURBANCE:

Frequency of Potential Contact:

X High

Moderate

Low

Description: Material is located in high traffic areas.

Influence of Vibration:

High

Moderate

X Low

Description:

None identified.

Potential for Air Erosion:

High

Moderate

X Low

Description:

None identified.

OVERALL RATING:

 $\underline{\mathbf{X}}$ Potential for

Potential for

Low Potential for

Significant Damage

Damage

Damage

COMMENTS:

Material should be removed prior to renovation or demolition.

BAT Associates, Inc.

17

BUILDING: Charleston Naval Shipyard, Building Number 36

SAMPLE NUMBER(S): 36-5-1

HOMOGENEOUS AREA No.: 5

TYPE OF MATERIAL:

Surfacing

TSI

X Other

Description: Floor Tile, 12" x 12" lime green with white streaks w/ black mastic

Approximate Amount of Asbestos-Containing Material (Linear or Square Foot): 7,000 SF

CONDITION:

Percent Damage:

<1 % Damage

Localized

Distributed

Type of Damage:

Deterioration

Water

Physical

DESCRIPTION:

Overall Rating:

X Good

Fair

Poor

POTENTIAL FOR DISTURBANCE:

Frequency of Potential Contact:

X High

Moderate

Low

Description: Material is located in high traffic areas.

Influence of Vibration:

High

Moderate

X Low

Description:

None identified.

Potential for Air Erosion:

High

Moderate

X Low

Description:

None identified.

OVERALL RATING:

X Potential for

Potential for

Low Potential for

Significant Damage

Damage

Damage

COMMENTS:

BUILDING: Charleston Naval Shipyard, Building Number 36

SAMPLE NUMBER(S): 33-3-1, 33-3-2, and 33-3-3

HOMOGENEOUS AREA No.: 13

TYPE OF MATERIAL: Surf

Surfacing

X TSI

Other

Description: Pipe Fitting Insulation, 3" with canvas wrap on steam

Approximate Amount of Asbestos-Containing Material (Linear or Square Foot): 300 EA

CONDITION:

Percent Damage:

<1 % Damage

Localized

Distributed

Type of Damage:

Deterioration

Water

Physical

DESCRIPTION:

Overall Rating:

X Good

Fair

Poor

POTENTIAL FOR DISTURBANCE:

Frequency of Potential Contact:

High

X Moderate

Low

Description: Material is located in near walls.

Influence of Vibration:

High

Moderate

X Low

Description:

None identified.

Potential for Air Erosion:

High

Moderate

X Low

Description:

None identified.

OVERALL RATING:

Potential for

X Potential for

Low Potential for

Significant Damage

Damage

Damage

COMMENTS: <u>Material should be removed prior to renovation or demolition.</u>

BAT Associates, Inc.

19

BUILDING: Charleston Naval Shipyard, Building Number 36

SAMPLE NUMBER(S): Assumed to contain asbestos

HOMOGENEOUS AREA No.: 14

TYPE OF MATERIAL: Surfacing

 \mathbf{X} TSI

Other

Description: Pipe Fitting Insulation, 3" with canvas wrap on domestic water

Approximate Amount of Asbestos-Containing Material (Linear or Square Foot): 375 EA

CONDITION:

Percent Damage:

UNK % Damage

Localized

Distributed

Type of Damage:

Deterioration

Water

Physical

DESCRIPTION:

Overall Rating:

UNK Good

Fair

Poor

POTENTIAL FOR DISTURBANCE:

Frequency of Potential Contact:

High

Moderate

X Low

Description: Material is located in walls.

Influence of Vibration:

High

Moderate

X Low

Description:

None identified.

Potential for Air Erosion:

High

Moderate

X Low

Description:

None identified.

OVERALL RATING:

Potential for

Potential for

 $\underline{\mathbf{X}}$ Low Potential for

Significant Damage

Damage

Damage

COMMENTS:

Material should be removed prior to renovation or demolition.

BAT Associates, Inc.

20

BUILDING: Charleston Naval Shipyard, Building Number 36

SAMPLE NUMBER(S): Exterior Pipe-32

HOMOGENEOUS AREA No.: 17

TYPE OF MATERIAL:

Surfacing

X TSI

Other

Description: Pipe Insulation, 12" with metal wrap

Approximate Amount of Asbestos-Containing Material (Linear or Square Foot): 160 LF

CONDITION:

Percent Damage:

0 % Damage

Localized

Distributed

Type of Damage:

X Deterioration

Water

Physical

DESCRIPTION:

Overall Rating:

Good

X Fair

Poor

POTENTIAL FOR DISTURBANCE:

Frequency of Potential Contact:

High

X Moderate

Low

Description: Majority of material is located above head level.

Influence of Vibration:

High

Moderate

X Low

Description:

None identified.

Potential for Air Erosion:

High

Moderate

X Low

Description:

None identified.

OVERALL RATING:

Potential for

 \mathbf{X} Potential for

Low Potential for

Significant Damage

Damage

Damage

COMMENTS: <u>Material should be removed prior to renovation or demolition.</u>

BAT Associates, Inc.

21

9.0 HAZARD ASSESSMENT OF IDENTIFIED ACM

AHERA describes a hazard assessment as "the means of collecting and considering whatever data were necessary for the management planner to make an informed, responsible recommendation to the LEA [Local Education Agency] consistent with response action requirements". As stated in AHERA, there is no single assessment method that is required in the regulations.


BAT adopted for this re-inspection one of the four general classes of hazard assessment models considered during the AHERA rule-making process. This method for hazard assessment is a modified decision tree as detailed in the USEPA, *Guidance for Assessing and Managing Exposure to Asbestos in Buildings*, or the *Pink Book*. Based on the physical assessment responses documented in the field, the BAT Management Planner proceeded through the decision tree process depicted in Figure 1.0 on the following page.

Only the identified and/or assumed asbestos-containing materials were assessed for hazards.

All of the identified and/or assumed asbestos-containing materials observed in this building were in good condition on the day of the survey.

Figure 1.0 Decision Tree Diagram For Hazard Assessment

Hazard rank #1 are materials of highest concern, and hazard rank #7 are the materials least likely to release asbestos fibers to the work area.



^{*}Miscellaneous materials that are considered non-friable were placed in the Hazard Rank #8 category, which is in good condition with a low potential for damage.

HAZARD ASSESSMENT AND RESPONSE ACTION DATA FOR IDENTIFIED ACM

BUILDING: Charleston Naval Shipyard, Building Number 36

SAMPLE NUMBER(S): 31-5-1

HOMOGENEOUS AREA No.: $\underline{1}$

TYPE OF MATERIAL:

Surfacing

TSI

 \mathbf{X}

X Other

Description: Floor Tile, 9" x 9" black w/ black mastic

Approximate Amount of Asbestos-Containing Material (Linear or Square Foot): 14,000 SF

Approximate Recommended Response Action Cost:

HAZARD ASSESSMENT

RESPONSE ACTION RECOMMENDATION

(1) Significantly damaged

(2) Damaged plus potential for significant damage

(3) Damaged plus potential for damage

(4) Damaged plus low potential for damage

(5) ACM (good condition) with potential for significant damage

(6) ACM (good condition) with potential for damage

(7) Any remaining friable ACM or friable suspect ACM

X (8) Non-friable ACM

ESTONSE ACTION RECOMMENDATION

(1) Removal(2) Encapsulation

(3) Enclosure

(4) Repair

(5) Operations and Maintenance Program

HAZARD ASSESSMENT AND RESPONSE ACTION DATA FOR IDENTIFIED ACM

BUILDING: Charleston Naval Shipyard, Building Number 36

SAMPLE NUMBER(S): 31-2-1

HOMOGENEOUS AREA No.: 3

TYPE OF MATERIAL:

Surfacing

TSI

X

Other

Description: Floor Tile, 12" x 12" off-white with brown streaks w/ black mastic

Approximate Amount of Asbestos-Containing Material (Linear or Square Foot): 7,000 SF

Approximate Recommended Response Action Cost:

HAZARD ASSESSMENT

RESPONSE ACTION RECOMMENDATION

(1) Significantly damaged

(2) Damaged plus potential for significant damage

(3) Damaged plus potential for damage

(4) Damaged plus low potential for damage

(5) ACM (good condition) with potential for significant damage

(6) ACM (good condition) with potential for damage

(7) Any remaining friable ACM or friable suspect ACM

X (8) Non-friable ACM

(2) Encapsulation

(3) Enclosure

(1) Removal

(4) Repair

(5) Operations and Maintenance Program

HAZARD ASSESSMENT AND RESPONSE ACTION DATA FOR IDENTIFIED ACM

BUILDING: Charleston Naval Shipyard, Building Number 36

SAMPLE NUMBER(S): 36-4-1

HOMOGENEOUS AREA No.: 4

TYPE OF MATERIAL:

Surfacing

TSI

X Other

Description: Floor Tile, 12" x 12" beige with gray speckles w/ black mastic

Approximate Amount of Asbestos-Containing Material (Linear or Square Foot): 7,240 SF

Approximate Recommended Response Action Cost:

HAZARD ASSESSMENT

RESPONSE ACTION RECOMMENDATION

- (1) Significantly damaged
- (2) Damaged plus potential for significant damage
- (3) Damaged plus potential for damage
- (4) Damaged plus low potential for damage
- (5) ACM (good condition) with potential for significant damage
- (6) ACM (good condition) with potential for damage
- (7) Any remaining friable ACM or friable suspect ACM
- X (8) Non-friable ACM

X (1) Removal

- (2) Encapsulation
 - (3) Enclosure
 - (4) Repair
 - (5) Operations and Maintenance Program

HAZARD ASSESSMENT AND RESPONSE ACTION DATA FOR IDENTIFIED ACM

BUILDING: Charleston Naval Shipyard, Building Number 36

SAMPLE NUMBER(S): 36-5-1

HOMOGENEOUS AREA No.: <u>5</u>

TYPE OF MATERIAL:

Surfacing

TSI

X

X Other

Description: Floor Tile, 12" x 12" lime green with white streaks w/ black mastic

Approximate Amount of Asbestos-Containing Material (Linear or Square Foot): 7,000 SF

Approximate Recommended Response Action Cost:

HAZARD ASSESSMENT

RESPONSE ACTION RECOMMENDATION

(1) Significantly damaged

(2) Damaged plus potential for significant damage

(3) Damaged plus potential for damage

(4) Damaged plus low potential for damage

(5) ACM (good condition) with potential for significant damage

(6) ACM (good condition) with potential for damage

(7) Any remaining friable ACM or friable suspect ACM

X (8) Non-friable ACM

RESPONSE ACTION RECOMMENDATION

(2) Encapsulation

(3) Enclosure

(1) Removal

(4) Repair

(5) Operations and Maintenance Program

HAZARD ASSESSMENT AND RESPONSE ACTION DATA FOR IDENTIFIED ACM

BUILDING: Charleston Naval Shipyard, Building Number 36

SAMPLE NUMBER(S): 33-3-1, 33-3-2, and 33-3-3

HOMOGENEOUS AREA No.: 13

TYPE OF MATERIAL:

Surfacing

X TSI

Other

Description: Pipe Fitting Insulation, 3" white with canvas wrap on steam

Approximate Amount of Asbestos-Containing Material (Linear or Square Foot): 300 EA

Approximate Recommended Response Action Cost:

HAZARD ASSESSMENT

- (1) Significantly damaged
- (2) Damaged plus potential for significant damage
- (3) Damaged plus potential for damage
- \mathbf{X} (4) Damaged plus low potential for damage
 - (5) ACM (good condition) with potential for significant damage
 - (6) ACM (good condition) with potential for damage
 - (7) Any remaining friable ACM or friable suspect ACM
 - (8) Non-friable ACM

- (1) Removal \mathbf{X}
 - (2) Encapsulation

RESPONSE ACTION RECOMMENDATION

- (3) Enclosure
- (4) Repair
- (5) Operations and Maintenance Program

HAZARD ASSESSMENT AND RESPONSE ACTION DATA FOR IDENTIFIED ACM

BUILDING: Charleston Naval Shipyard, Building Number 36

SAMPLE NUMBER(S): Assumed to contain asbestos

HOMOGENEOUS AREA No.:

14

TYPE OF MATERIAL:

Surfacing

X TSI

Other

Description: Pipe Fitting Insulation, 3" with canvas wrap on domestic water

Approximate Amount of Asbestos-Containing Material (Linear or Square Foot): 375 EA

Approximate Recommended Response Action Cost:

HAZARD ASSESSMENT

RESPONSE ACTION RECOMMENDATION

- (1) Significantly damaged
- (2) Damaged plus potential for significant damage
- (3) Damaged plus potential for damage
- (4) Damaged plus low potential for damage
- (5) ACM (good condition) with potential for significant damage
- (6) ACM (good condition) with potential for damage
- (7) Any remaining friable ACM or friable suspect ACM
- (8) Non-friable ACM

- (1) Removal \mathbf{X}
 - (2) Encapsulation
 - (3) Enclosure
 - (4) Repair
 - (5) Operations and Maintenance Program

COMMENTS: Material should be removed prior to renovation or demolition.

HAZARD ASSESSMENT AND RESPONSE ACTION DATA FOR IDENTIFIED ACM

BUILDING: Charleston Naval Shipyard, Building Number 36

SAMPLE NUMBER(S): Exterior Pipe-32

HOMOGENEOUS AREA No.: 17

TYPE OF MATERIAL:

Surfacing

X TSI

Other

Description: Pipe Insulation, 12" with metal wrap

Approximate Amount of Asbestos-Containing Material (Linear or Square Foot): 160 LF

Approximate Recommended Response Action Cost:

HAZARD ASSESSMENT

RESPONSE ACTION RECOMMENDATION

(1) Significantly damaged

(2) Damaged plus potential for significant damage

 \mathbf{X} (3) Damaged plus potential for damage

- (4) Damaged plus low potential for damage
- (5) ACM (good condition) with potential for significant damage
- (6) ACM (good condition) with potential for damage
- (7) Any remaining friable ACM or friable suspect ACM
- (8) Non-friable ACM

(1) Removal X

- (2) Encapsulation
- (3) Enclosure
- (4) Repair
- (5) Operations and Maintenance Program

COMMENTS: Material should be removed prior to renovation or demolition.

10.0 PRELIMINARY COST ESTIMATE FOR REMOVAL OF IDENTIFIED ACM

The following is a preliminary cost estimate for the abatement (removal) of identified ACM in Building 36. This estimate is based on removing all of the materials during the same project. It does not include the cost of replacement materials. The cost estimate includes, project surveillance, air monitoring, and disposal of materials. These costs are estimates only; BAT made no attempt to obtain bids from removal contractors for this work, however, the average unit costs of three asbestos abatement contractors were used to develop the preliminary removal costs. Additionally, quantities noted are based upon engineering measurements. BAT recommends the use of architectural measurements for more accurate quantification.

			Total
	Unit		Abatement
Material Description	Cost (\$)	Quantity	Cost (\$)
Floor Tile (multi-layers) with Mastic	2.78	21,000 SF	58,380
Pipe Insulation (25-30 feet above ground)	5.25	160 LF	840
Pipe Fitting Insulation (including demolition of walls)	32.59	675 EA	21,998
Handling Cost	25.00	134 EA	3,350
Mobilization	300.00	3 EA	900
Waste Disposal Cost	<u>50.00</u>	<u>8 CY</u>	<u>400</u>
Removal Subtotal			85,868
IH Supervision and Monitoring			10,500
Project Subtotal			96,368
Contingency (35%)			33,729
Project Total			130,097

SF = Square Feet LF = Linear Feet EA = Each CY = Cubic Yard

11.0 CONCLUSIONS

Inspection of Building 36 and confirmatory laboratory bulk sample analysis of selected samples identified the following materials with asbestos concentrations greater than one percent.

Identified ACM	Quantity	NESHAP Category
Floor Tile, 9" x 9" black w/ black mastic Floor Tile, 12" x 12" off-white with brown streaks w/ black	14,000 SF 7,000 SF	Category I, non-friable Category I, non-friable
mastic Floor Tile, 12" x 12" beige with gray speckles w/ black mastic	7,240 SF	Category I, non-friable
Floor Tile, 12" x 12" lime green with white streaks w/ black mastic	7,000 SF	Category I, non-friable
Pipe Fitting Insulation, 3" white with canvas wrap on steam Pipe Insulation, 12" with metal wrap	300 EA 160 LF	Regulated, friable Regulated, friable


The following materials were not sampled in order to avoid disrupting their integrity, and they were assumed to contain asbestos:

Assumed ACM	Quantity	NESHAP Category
Pipe Fitting Insulation, 3" with canvas wrap on domestic water	375 EA	Regulated, friable

Other suspect ACM not identified could be present in areas of the building inaccessible to the asbestos-building inspectors. For example, material could exist in walls and other locations where access could only be gained by demolition of the building. Also, other materials currently not recognized as ACM by the asbestos building inspection industry could exist.

Rooms that were inaccessible to the asbestos-building inspectors have been identified on the drawings of the building in Appendix B, Sample and ACM Location Drawings.

EPA rules governing the application, removal and disposal of ACM were promulgated under NESHAP [40 CFR 61 Part M]. NESHAP requires the building owner or asbestos removal contractor to notify EPA when a building containing ACM is to be removated, ACM is to be removed, or the building is to be demolished. At least 20 days notification is required "...if less than 260 linear feet of asbestos pipe covering or 160 square feet of asbestos material are removed during building renovation". Ten days notification is required when the amount is greater than 260 linear feet or 160 square feet of friable ACM.



LEGEND

- Sample Location
- (-) Non-Asbestos-Containing Sample Location
- (+) Asbestos-Containing Sample Location
- Asbestoe-Containing Floor Tile and Mastic
- Pipe Fitting Insulation on Riser and Branches to Radiator
- Asbestos-Containing
 Pipe Fitting Insulation
 on Domestic Water
 (Inaccessible in Walls)

BUILDING 36 FIRST FLOOR


Sample and Asbeetos-Containing Material Locations





BAT Associates, Inc.

ENVIRONMENTAL, HEALTH & SAFETY SERVICES 5151 BROOK HOLLOW PARKWAY, SUITE 250 NORCROSS, GA 30071



LEGEND

- Sample Location
- (-) Non-Asbestos-Containing Sample Location



- Asbestos-Containing Pipe Fitting Insulation on Riser and Branches to Radiator
- o- Asbestos-Containing Pipe Fitting Insulation on Domestic Water (Inaccessible in Walls)

BUILDING 36


SECOND FLOOR

Sample and Asbestoe-Containing Material Locations





BAT Associates, Inc. ENVIRONMENTAL, HEALTH & SAFETY SHRVICES 5151 BROOK HOLLOW PARKWAY, SUITE 250 NORCROSS, GA 30071



LEGEND

- Sample Location
- (-) Non-Asbestos-Containing Sample Location
- (+) Asbestos-Containing Sample Location



- Asbestos-Containing
 Pipe Fitting Insulation
 on Riser and Branches
 to Radiator
- Asbestos-Containing
 Pipe Fitting Insulation
 on Domestic Water
 (Inaccessible in Walls)

BUILDING 36

THIRD FLOOR

Sample and Asbestos-Containing Material Locations





BAT Associates, Inc.

ENVIRONMENTAL, HEALTH & SAFETY SERVICES 5151 BROOK HOLLOW PARKWAY, SUITE 250 NORCROSS, GA 30071

Floor Tile, 9" x 9" black w/ black mastic, HA # 1



Floor Tile, 12" x 12" off-white with brown streaks w/ black mastic, HA # 3



Floor Tile, 12" x 12" beige with gray speckles w/ black mastic, HA # 4



Floor Tile, 12" x 12" lime green with white streaks w/ black mastic, HA # 5



Pipe Fitting Insulation, 3" white with canvas wrap on steam, HA # 13

INACCESSIBLE IN WALLS

Pipe Fitting Insulation, 3" with canvas wrap on domestic water, HA # 14

Pipe Insulation, 12" with metal wrap, HA # 17





The Georgia Institute of Technology

This is to certify that

Foshie Bell

has attended an EPA-approved half-day Continuing Education Course entitled:

Inspecting Buildings for Asbestos Containing Materials (Annual Refresher Course for Building Inspectors)

> as required by the Federal EPA AHERA Model Accreditation Plan for re-accreditation as a Building Inspector for Asbestos (TSCA Title II).

> > Georgia Tech Research Institute Electro-Optics, Environment and Materials Laboratory Atlanta, GA 30332 Phone: (404) 894-7430; FAX: (404) 894-1267

August 26, 1998

Dates of Attendance

August 26, 1999

Expiration Date

149-64-0385

Social Security Number

Tyftle I. Turner, CET

Course Director

2900

Certificate Number

The Environmental Institute

Douglas J. Milton

Has completed coursework and satisfactorily passed an examination that meets all criteria required for EPA/AHERA/ASHARA (TSCA Title II) Approved Reaccreditation and NESHAP Regulations Training

Asbestos in Buildings: Inspector & Management Planner Refresher

December 15, 1999
Course Date

December 15, 1999
Examination Date

December 14, 2000
Expiration Date

TEI - 1300 William's Drive, Suite E - Marietta, Georgia 30066 - (770) 427-3600

The

American Board of Industrial Hygiene® ABIH®



organized to improve the practice of Industrial Hygiene proclaims that

Douglas J. Milton

having met all requirements through education, experience and examination, is hereby certified in the

COMPREHENSIVE PRACTICE of INDUSTRIAL HYGIENE

and has the right to use the designations

CERTIFIED INDUSTRIAL HYGIENIST

CIH

November 12, 1997

date

Chair ABIH

CP 7612

certificate number Secretary ABIH



ASBESTOS ABATEMENT LICENSE



No. 22860

This certifies that

Douglas J Wilton

266-000-7179

doing business as B Ch T Chssociates, Inc

has satisfactorily completed the training required by South Carolina Regulation No. 61-86.1 and the EPA Model Accreditation Plan, 40 CFR 763 Subpart E Appendix C, for the category of

Consultant/Wanagement Slanner

The holder of this license shall comply with all the requirements of said Regulation.

This License, License Number, or any Representation thereof, is not transferable to any other licensee or company. Use of this License is only authorized for the licensee and Company whose name appears hereon and shall expire one year from

> The holder of this license is qualified in accordance with requirements of the Asbestos Hazard Emergency Response Act of 1986 (AHERA) to perform as an abatement Building Inspector.

07/28/99

ORIGINAL

07/28/99 14:31



Air Compliance Management Division

Bureau of Air Quality

South Carolina Department of Health & Environmental Control



ASBESTOS ABATEMENT LICENSE

No. 22859

This certifies that

Douglas J Wilton

266-BA-7179

doing business as B A T Associates, Inc

has satisfactorily completed the training required by South Carolina Regulation No. 61-86.1 and the EPA Model Accreditation Plan, 40 CFR 763 Subpart E Appendix C, for the category of

Consultant/Building Inspector

The holder of this license shall comply with all the requirements of said Regulation.

This License, License Number, or any Representation thereof, is not transferable to any other licensee or company. Use of this License is only authorized for the licensee and Company whose name appears hereon and shall expire one year from 09/23/98.

07/28/99

Richard D. Sharpe, Director


Air Compliance Management Division Bureau of Air Quality

Richard D. Thanks

CR-001126

South Carolina Department of Health & Environmental Control

United States Department of Commerce National Institute of Standards and Technology



ISO/IEC GUIDE 25:1990 ISO 9002:1987

Certificate of Accreditation



ANALYTICAL ENVIRONMENTAL SERVICES, INC. ATLANTA, GA

is recognized under the National Voluntary Laboratory Accreditation Program for satisfactory compliance with criteria established in Title 15, Part 285 Code of Federal Regulations. These criteria encompass the requirements of ISO/IEC Guide 25 and the relevant requirements of ISO 9002 (ANSI/ASQC Q92-1987) as suppliers of calibration or test results. Accreditation is awarded for specific services, listed on the Scope of Accreditation for:

BULK ASBESTOS FIBER ANALYSIS

September 30, 2000

Effective through

For the National Institute of Standards and Technology

NVLAP Lab Code: 102033-0

United States Department of Commerce National Institute of Standards and Technology



CAPE ENVIRONMENTAL MANAGEMENT, INC. ATLANTA, GA

is recognized under the National Voluntary Laboratory Accreditation Program for satisfactory compliance with criteria established in Title 15, Part 285 Code of Federal Regulations. These criteria encompass the requirements of ISO/IEC Guide 25 and the relevant requirements of ISO 9002 (ANSI/ASQC Q92-1987) as suppliers of calibration or test results. Accreditation is awarded for specific services, listed on the Scope of Accreditation for:

BULK ASBESTOS FIBER ANALYSIS


June 30, 2000

Effective through

For the National Institute of Standards and Technology

NVLAP Lab Code: 102111-0

ISO 9002:1987



2302 PARKLAKE DRIVE, SUITE 200, ATLANTA, GA 30345 TEL: (770) 908-7200 FAX: (770) 908-7219 NYLAP ®

ACCREDITED
LAB CODE - 102111

POLARIZED LIGHT MICROSCOPY (PLM) BULK SAMPLE ANALYSIS REPORT

CLIENT NAME:	BAT ASSOCIATES	LAB JOB NO:	B9334-2
PROJECT NAME:	CHARLESTON NSY / 971001-13.03	DATE RECEIVED:	12/16/99
PROJECT NO: L802Z.000		REPORT ISSUED:	1/13/00
SAMPLE FIELD ID:	31-5-1	LAB ID:	928071
SAMPLE INFO:		DATE ANALYZED:	1/10/00
	SAMPLE DESCRIPT	ON	
LAYERED: NO			
APPEARANCE:	BLACK HARD SILTY TO GRANULAR (FT) WI	TH FIBERS AND BROWN MAS	STIC

RESULT OF ANALYSIS IN VOLUME PERCENTAGE (BY VISUAL ESTIMATE)

ASBESTOS FIB	ERS	NONASBESTOS FIBERS	NONFIBROUS COMPONENTS	OTHER COMPO	NENTS
CHRYSOTILE	7	CELLULOSE	VERMICULITE/MICA	BITUMEN/TAR	T
AMOSITE		GLASS FIBERS	PERLITE	SAND/AGGR.	20
CROCIDOLITE		SYNTHETICS	EXPANDED GLASS	GLUE/CAULK	5
TREMOLITE		WOLLASTONITE	SYNTHETIC FOAM	VINYL	T
ACTINOLITE		TALC	ALUMINUM/METAL	CORK	
ANTHOPHYLLITE		FOAM RUBBER	LATEX/RUBBER	1	
				PAINT/OTHER	68

COMMENTS: 2% CHRYSOTILE IN MASTIC

SAMPLE WAS ANALYZED BY PLM USING DISPERSION STAINING TECHNIQUES IN ACCORDANCE WITH U.S. EPA
METHOD 40CFR Ch. I (7-1-92) PT. 763, SUBPT. F, APP. A. LAST CALIBRATION OF EQUIPMENT WAS PERFORMED ON: 1/10/00
FOR ALL HETEROGENEOUS AND LAYERED SAMPLES EASILY SEPARATED INTO SUBLAYERS, EACH LAYER IS ANALYZED SEPARATELY.
REPORT 1 OF 1

ANALYST

STEVE INDIVIS

QUALITY/CONTROL

ALEKSEY REZNIK

PLM IS NOT CONSISTENTLY RELIABLE IN DETECTING SMALL CONCENTRATION OF ASBESTOS IN FLOOR TILES AND SIMILAR NOTFRIABLE MATERIALS, QUANTITATIVE TEM IS CURRENTLY THE ONLY METHOD THAT CAN BE USED TO GET THE CONCLUSIVE ASBESTOS CONTENT. THIS REPORT RELATES ONLY TO THE ITEMS ISSTED. THIS REPORT SHALL NOT BE REPORDUCED EXCEPT IN FULL, AND NOT WITHOUT WRITTEN APPROVAL OF THE LABORATORY. THIS REPORT SHALL NOT BE USED TO CLAIM ENDORSEMENT BY INVLAP OR ANY AGENCY OF U.S. GOVERMENT



ANALYTICAL ENVIRONMENTAL SERVICES, INC. 3125 Marjan Drive

Atlanta, GA 30340 Tel: (770) 457-8177 Fax: (770) 457-8188 AES Job Number: B212 Page 68 of 183 Total Samples Wednesday, February 09, 2000



BULK SAMPLE ANALYSIS

Client Name:

B A T Associates, Inc.

Project Name:

Charleston Naval Shipyard

Project Number

971001

Client Sample ID:

32-2-1

AES Lab ID:

3438

Location:

Not given

Sample Description: Green hard compact partly granular with fibers, glue and paint.

All p	percentages g	ven below are visually estimated by volume	
ASBESTOS F	FIBERS	NON-FIBROUS MAT	TERIALS
Chrysotile:		Vermiculite:	
Amosite:		Biotite:	
Crocidolite:		Mica:	
Anthophyllite:		Perlite:	
Tremolite:		Aggregates:	45
Actinolite:		Styrofoam:	
NON-ASBESTO	S FIBERS	OTHERS	
Synthetics:	1	Aluminum:	
Mineral Wool:		Bitumen:	
Fiberglass:		Resilient Material:	
Cellulose:	1	Glue:	3
Animal Hair:		Binders:	50
Antigorite:			

COMMENTS: Paint included as binder.

It is certified by the signatures below that the laboratory identified is accredited by the National Institute of Standards and Technology for Polarized Light Microscopy (PLM) analysis under the EPA Interim Asbestos Bulk Sample Quality Assurance Program, Laboratory 102082-0.

Microanalyst:

Svetlana Arkhipov

QCAnalyst:

Andrew Pittman



ANALYTICAL ENVIRONMENTAL SERVICES, INC. 3125 Marjan Drive

Atlanta, GA 30340 Tel: (770) 457-8177 Fax: (770) 457-8188 AES Job Number: B212 Page 69 of 183 Total Samples Wednesday, February 09, 2000



BULK SAMPLE ANALYSIS

Client Name:

B A T Associates, Inc.

Project Name:

Charleston Naval Shipyard

Project Number

971001

Client Sample ID:

32-2-2

AES Lab ID:

3439

Location:

Not given

Sample Description: Green hard compact partly granular with fibers, glue and paint.

Al	ll percentages g	iven below are visually estimated by volume	
ASBESTOS FIBERS		NON-FIBROUS MA	TERIALS
Chrysotile:		Vermiculite:	
Amosite:		Biotite:	
Crocidolite:		Mica:	
Anthophyllite:		Perlite:	
Tremolite:		Aggregates:	45
Actinolite:		Styrofoam:	
NON-ASBEST	OS FIBERS	OTHERS	
Synthetics:	1	Aluminum:	
Mineral Wool:		Bitumen:	
Fiberglass:		Resilient Material:	
Cellulose:	1	Glue:	3
Animal Hair:		Binders:	50
Antigorite:			

COMMENTS: Paint included as binder.

Svetlana Arkhipov

it is certified by the signatures below that the laboratory identified is accredited by the National Institute of Standards and Technology for Polarized Light Microscopy (PLM) analysis under the EPA Interim Asbestos Bulk Sample Quality Assurance Program, Laboratory 102082-0.

Microanalyst:

3

QCAnalyst:

Andrew Pittman



ANALYTICAL ENVIRONMENTAL SERVICES, INC. 3125 Marjan Drive

Atlanta, GA 30340 Tel: (770) 457-8177

Fax: (770) 457-8188

AES Job Number: **B212** Page 70 of 183 Total Samples Wednesday, February 09, 2000



BULK SAMPLE ANALYSIS

Client Name:

BAT Associates, Inc.

Project Name:

Charleston Naval Shipyard

Project Number

971001

Client Sample ID:

32-2-3

AES Lab ID:

3440

Location:

Not given

Sample Description: Green hard compact partly granular with fibers, glue and paint.

All percentages given below are visually estimated by volume					
ASBESTOS	FIBERS	NON-FIBROUS MA	TERIALS		
Chrysotile:		Vermiculite:			
Amosite:		Biotite:			
Crocidolite:		Mica:			
Anthophyllite:		Perlite:			
Tremolite:		Aggregates:	45		
Actinolite:	,	Styrofoam:			
NON-ASBESTO	S FIBERS	OTHERS			
Synthetics:	1	Aluminum:			
Mineral Wool:		Bitumen:			
Fiberglass:		Resilient Material:			
Cellulose:	1	Glue:	3		
Animal Hair:		Binders:	50		
Antigorite:					

COMMENTS: Paint included as binder.

it is certified by the signatures below that the laboratory identified is accredited by the National Institute of Standards and Technology for Polarized Light Microscopy (PLM) analysis under the EPA Interim Asbestos Bulk Sample Quality Assurance Program, Laboratory 102082-0.

Microanalyst

QCAnalyst



3125 Marjan Drive Atlanta, GA 30340 Tel: (770) 457-8177

Fax: (770) 457-8188

AES Job Number: Page 133 of 183 Total Samples Wednesday, February 09, 2000



BULK SAMPLE ANALYSIS

Client Name:

B A T Associates, Inc.

Project Name:

Charleston Naval Shipyard

Project Number

971001

Client Sample ID:

31-2-1

AES Lab ID:

3503

Location:

Not given

Sample Description: Red hard compact partly granular with fibers and glue.

All p	All percentages given below are visually estimated by volume				
ASBESTOS F	FIBERS	NON-FIBROUS MA	TERIALS		
Chrysotile:	10	Vermiculite:			
Amosite:		Biotite:			
Crocidolite:		Mica:			
Anthophyllite:		Perlite:			
Tremolite:		Aggregates:	45		
Actinolite:		Styrofoam:			
NON-ASBESTO	S FIBERS	OTHERS			
Synthetics:	1	Aluminum:			
Mineral Wool:		Bitumen:			
Fiberglass:		Resilient Material:			
Cellulose:	1	Glue:	3		
Animal Hair:		Binders:	40		
Antigorite:					

COMMENTS: Floor tile contains 10% chrysotile. Glue contains 1-2% chrysotile.

It is certified by the signatures below that the laboratory identified is accredited by the National Institute of Standards and Technology for Polarized Light Microscopy (PLM) analysis under the EPA Interim Asbestos Bulk Sample Quality Assurance Program, Laboratory 102082-0.

Microanalyst:

Svetlana Arkhipov

QCAnalyst

Andrew Pittman



3125 Marjan Drive Atlanta, GA 30340 Tel: (770) 457-8177

Fax: (770) 457-8177

AES Job Number: B212 Page 41 of 183 Total Samples Thursday, February 10, 2000



BULK SAMPLE ANALYSIS

Client Name:

BAT Associates, Inc.

Project Name:

Client Sample ID:

Charleston Naval Shipyard

36-4-1

Location:

Not given

Project Number

971001

AES Lab ID:

3411

Sample Description: Gray hard compact partly granular with fibers, bitumen and glue.

All percentages given below are visually estimated by volume

ASBESTOS F	IBERS	NON-FIBROUS MAT	ERIALS
Chrysotile:	3	Vermiculite:	
Amosite:		Biotite:	
Crocidolite:		Mica:	
Anthophyllite:		Perlite:	_
Tremolite:		Aggregates:	45
Actinolite:		Styrofoam:	
NON-ASBESTO	S FIBERS	OTHERS	
Synthetics:	1	Aluminum:	
Mineral Wool:		Bitumen:	3
Fiberglass:		Resilient Material:	
Cellulose:	1	Glue:	2
Animal Hair:		Binders:	45
Antigorite:			-

COMMENTS:

Floor tile contains 3 % chrysotile. Bitumen contains 5 % chrysotile. Glue does not

contain asbestos.

It is certified by the signatures below that the laboratory identified is accredited by the National Institute of Standards and Technology for Polarized Light Microscopy (PLM) analysis under the EPA Interim Asbestos Bulk Sample Quality Assurance Program, Laboratory 102082-0.

Microanalyst:

QCAnalyst

Andrew Pittman



3125 Marjan Drive Atlanta, GA 30340 Tel: (770) 457-8177

Fax: (770) 457-8188

AES Job Number: B212 Page 44 of 183 Total Samples Wednesday, February 09, 2000



BULK SAMPLE ANALYSIS

Client Name:

BAT Associates, Inc.

Project Name:

Charleston Naval Shipyard

Project Number

971001

Client Sample ID:

36-5-1

AES Lab ID:

3414

Location:

Not given

Sample Description: Light green hard compact partly granular with fibers and bitumen.

All	l percentages g	iven below are visually estimated by volume	
ASBESTOS FIBERS		NON-FIBROUS MA	TERIALS
Chrysotile:	5	Vermiculite:	
Amosite:		Biotite:	
Crocidolite:		Mica:	
Anthophyllite:		Perlite:	
Tremolite:		Aggregates:	45
Actinolite:		Styrofoam:	
NON-ASBEST	OS FIBERS	OTHERS	
Synthetics:	1	Aluminum:	
Mineral Wool:		Bitumen:	2
Fiberglass:		Resilient Material:	
Cellulose:	1	Glue:	
Animal Hair:		Binders:	46
Antigorite:			

COMMENTS: Floor tile contains 5 % chrysotile. Bitumen contains 10 % chrysotile.

Shipoc

Svetlana Arkhipov

It is certified by the signatures below that the laboratory identified is accredited by the National Institute of Standards and Technology for Polarized Light Microscopy (PLM) analysis under the EPA Interim Asbestos Bulk Sample Quality Assurance Program, Laboratory 102082-0.

Microanalyst:

QCAnalyst:

Andrew Pittman



ANALYTICAL ENVIRONMENTAL SERVICES, INC. 3125 Marjan Drive

Atlanta, GA 30340 Tel: (770) 457-8177

Fax: (770) 457-8188

AES Job Number: Page 142 of 183 Total Samples Wednesday, February 09, 2000



BULK SAMPLE ANALYSIS

Client Name:

BAT Associates, Inc.

Project Name:

Charleston Naval Shipyard

Project Number

971001

Client Sample ID:

31-10-1

AES Lab ID:

3512

Location:

Not given

Sample Description: Gray soft fibrous to perlitic with paint.

All percentages given below are visually estimated by volume

ASBESTOS F	IBERS	NON-FIBROUS MAT	NON-FIBROUS MATERIALS	
Chrysotile:		Vermiculite:		
Amosite:		Biotite:		
Crocidolite:		Mica:		
Anthophyllite:		Perlite:	30	
Tremolite:		Aggregates:		
Actinolite:		Styrofoam:		
NON-ASBESTO	S FIBERS	OTHERS		
Synthetics:		Aluminum:		
Mineral Wool:	35	Bitumen:		
Fiberglass:		Resilient Material:		
Cellulose:	25	Glue:		
Animal Hair:		Binders:	10	
Antigorite:				

COMMENTS: Paint included as binder.

Svetlana Arkhipov

It is certified by the signatures below that the laboratory identified is accredited by the National Institute of Standards and Technology for Polarized Light Microscopy (PLM) analysis under the EPA Interim Asbestos Bulk Sample Quality Assurance Program, Laboratory 102082-0.

Microanalyst:

QCAnalyst

Andrew Pittman



3125 Marjan Drive Atlanta, GA 30340 Tel: (770) 457-8177

Fax: (770) 457-8188

AES Job Number: B212 Page 143 of 183 Total Samples Wednesday, February 09, 2000



BULK SAMPLE ANALYSIS

Client Name:

BAT Associates, Inc.

Project Name:

Charleston Naval Shipyard

Project Number

971001

Client Sample ID:

31-10-2

AES Lab ID:

3513

Location:

Not given

Sample Description: Gray soft fibrous to perlitic with paint.

All percentages given below are visually estimated by volume **ASBESTOS FIBERS NON-FIBROUS MATERIALS** Vermiculite: Chrysotile: Amosite: Biotite: Crocidolite: Mica: Perlite: Anthophyllite: 30 Tremolite: Aggregates: Actinolite: Styrofoam: **NON-ASBESTOS FIBERS OTHERS** Synthetics: Aluminum: Mineral Wool: 35 Bitumen: Resilient Material: Fiberglass: 25 Glue: Cellulose: Animal Hair: Binders: 10 Antigorite:

COMMENTS: Paint included as binder. -

Ahripod

It is certified by the signatures below that the laboratory identified is accredited by the National Institute of Standards and Technology for Polarized Light Microscopy (PLM) analysis under the EPA Interim Asbestos Bulk Sample Quality Assurance Program, Laboratory 102082-0.

Microanalyst

QCAnalyst:

Andrew Pittman



3125 Marjan Drive Atlanta, GA 30340 Tel: (770) 457-8177 Fax: (770) 457-8188

AES Job Number: Page 144 of 183 Total Samples Wednesday, February 09, 2000



BULK SAMPLE ANALYSIS

Client Name:

B A T Associates, Inc.

Project Name: Client Sample ID: Charleston Naval Shipyard

31-10-3

Location:

Not given

Project Number

971001

AES Lab ID:

3514

Sample Description: Gray soft fibrous to perlitic.

All percentages given below are visually estimated by volume					
ASBESTOS F	IBERS	NON-FIBROUS MA	TERIALS		
Chrysotile:		Vermiculite:			
Amosite:		Biotite:			
Crocidolite:		Mica:			
Anthophyllite:		Perlite:	30		
Tremolite:		Aggregates:	1		
Actinolite:		Styrofoam:			
NON-ASBESTO	S FIBERS	OTHERS			
Synthetics:		Aluminum:			
Mineral Wool:	35	Bitumen:			
Fiberglass:		Resilient Material:			
Cellulose:	25	Glue:			
Animal Hair:		Binders:	10		
Antigorite:					

COMMENTS:

It is certified by the signatures below that the laboratory identified is accredited by the National Institute of Standards and Technology for Polarized Light Microscopy (PLM) analysis under the EPA Interim Asbestos Bulk Sample Quality Assurance Program, Laboratory 102082-0.

Microanalyst:

. Sektipos Svetlana Arkhipov

QCAnalyst

Andrew Pittman



3125 Marjan Drive Atlanta, GA 30340 Tel: (770) 457-8177

Fax: (770) 457-8188

AES Job Number: B212 Page 145 of 183 Total Samples Wednesday, February 09, 2000



BULK SAMPLE ANALYSIS

Client Name:

B A T Associates, Inc.

Project Name:

Client Sample ID:

Charleston Naval Shipyard

31-11-1

Location:

Not given

Project Number

971001

AES Lab ID:

3515

Sample Description: Gray soft fibrous to perlitic with paint.

All percentages given below are visually estimated by volume

ASBESTOS FIBERS		NON-FIBROUS MA	TERIALS
Chrysotile:		Vermiculite:	
Amosite:		Biotite:	
Crocidolite:		Mica:	
Anthophyllite:		Perlite:	30
Tremolite:		Aggregates:	
Actinolite:		Styrofoam:	
NON-ASBESTO	S FIBERS	OTHERS	
Synthetics:		Aluminum:	
Mineral Wool:	35	Bitumen:	
Fiberglass:		Resilient Material:	
Cellulose:	25	Glue:	
Animal Hair:		Binders:	10
Antigorite:			

COMMENTS: Paint included as binder. -

It is certified by the signatures below that the laboratory identified is accredited by the National Institute of Standards and Technology for Polarized Light Microscopy (PLM) analysis under the EPA Interim Asbestos Bulk Sample Quality Assurance Program, Laboratory 102082-0.

Microanalyst:

Svetlana Arkhipov

Atri poo

QCAnalyst

Andrew Pittman



3125 Marjan Drive Atlanta, GA 30340 Tel: (770) 457-8177

Fax: (770) 457-8188

AES Job Number: B212 Page 146 of 183 Total Samples Wednesday, February 09, 2000



BULK SAMPLE ANALYSIS

Client Name:

B A T Associates, Inc.

Project Name:

Charleston Naval Shipyard

Project Number

971001

Client Sample ID:

31-11-2

AES Lab ID:

3516

Location:

Not given

Sample Description: Gray soft fibrous to perlitic with paint.

All percentages given below are visually estimated by volume

ASBESTOS F	IBERS	NON-FIBROUS MA	T	
Chrysotile:		Vermiculite:	Vermiculite:	
Amosite:		Biotite:	1	
Crocidolite:		Mica:	Ť	
Anthophyllite:		Perlite:	Ť	
Tremolite:		Aggregates:	T	
Actinolite:		Styrofoam:		
NON-ASBESTO	S FIBERS	OTHERS		
Synthetics:		Aluminum:		
Mineral Wool:	35	Bitumen:	T	
Fiberglass:		Resilient Material:	T	
Cellulose:	25	Glue:		
Animal Hair:		Binders:	T	
Antigorite:			_	

COMMENTS: Paint included as binder. -

Svetlana Arkhipov

Lektripo

It is certified by the signatures below that the laboratory identified is accredited by the National Institute of Standards and Technology for Polarized Light Microscopy (PLM) analysis under the EPA Interim Asbestos Bulk Sample Quality Assurance Program, Laboratory 102082-0.

Microanalyst:

QCAnalyst:

Andrew Pittman



ANALYTICAL ENVIRONMENTAL SERVICES, INC. 3125 Marjan Drive

Atlanta, GA 30340 Tel: (770) 457-8177

Fax: (770) 457-8188

AES Job Number: B212 Page 147 of 183 Total Samples Wednesday, February 09, 2000



BULK SAMPLE ANALYSIS

Client Name:

BAT Associates, Inc.

Project Name:

Charleston Naval Shipyard

Client Sample ID: 31-11-3

Location:

Not given

Project Number

971001

AES Lab ID:

3517

Sample Description: Gray soft fibrous to perlitic with paint.

All p	ercentages g	ven below are visually estimated by volume	
ASBESTOS F	IBERS	NON-FIBROUS MA	TERIALS
Chrysotile:		Vermiculite:	
Amosite:		Biotite:	
Crocidolite:		Mica:	
Anthophyllite:		Perlite:	30
Tremolite:		Aggregates:	
Actinolite:		Styrofoam:	
NON-ASBESTO	S FIBERS	OTHERS	
Synthetics:		Aluminum:	
Mineral Wool:	35	Bitumen:	
Fiberglass:		Resilient Material:	
Cellulose:	25	Glue:	
Animal Hair:		Binders:	10
Antigorite:			

COMMENTS: Paint included as binder. -

It is certified by the signatures below that the laboratory identified is accredited by the National Institute of Standards and Technology for Polarized Light Microscopy (PLM) analysis under the EPA Interim Asbestos Bulk Sample Quality Assurance Program, Laboratory 102082-0.

Microanalyst:

Svetlana Arkhipov

whi food

QCAnalyst:

Andrew Pittman



3125 Marjan Drive Atlanta, GA 30340 Tel: (770) 457-8177 Fax: (770) 457-8188

AES Job Number: B212 Page 181 of 183 Total Samples Thursday, February 10, 2000



BULK SAMPLE ANALYSIS

Client Name:

BAT Associates, Inc.

Project Name:

Charleston Naval Shipyard

Project Number

971001

Client Sample ID:

34-19-1

AES Lab ID:

3551

Location: Not given

Sample Description: Black semi-hard bitumenous to silty with fibers.

All percentages given below are visually estimated by volume						
ASBESTOS F	IBERS	NON-FIBROUS MAT	ERIALS			
Chrysotile:		Vermiculite:				
Amosite:		Biotite:				
Crocidolite:		Mica:				
Anthophyllite:		Perlite:				
Tremolite:		Aggregates:				
Actinolite:		Styrofoam:				
NON-ASBESTO	S FIBERS	OTHERS				
Synthetics:	2	Aluminum:				
Mineral Wool:		Bitumen:	50			
Fiberglass:		Resilient Material:				
Cellulose:	1	Glue:				
Animal Hair:		Binders:	47			
Antigorite:						

COMMENTS:

It is certified by the signatures below that the laboratory identified is accredited by the National Institute of Standards and Technology for Polarized Light Microscopy (PLM) analysis under the EPA Interim Asbestos Bulk Sample Quality Assurance Program, Laboratory 102082-0.

Lehtipos

Microanalyst:

QCAnalyst:

Andrew Pittman



3125 Marjan Drive Atlanta, GA 30340 Tel: (770) 457-8177

Fax: (770) 457-8188

AES Job Number: B212
Page 182 of 183 Total Samples
Thursday, February 10, 2000



BULK SAMPLE ANALYSIS

Client Name:

BAT Associates, Inc.

Project Name:

Charleston Naval Shipyard

Project Number

971001

Client Sample ID:

34-19-2

AES Lab ID:

3552

Location:

Not given

Sample Description: Black semi-hard bitumenous to silty with fibers.

All percentages given below are visually estimated by volume						
ASBESTOS FIBER	RS	NON-FIBROUS MAT	ERIALS			
Chrysotile:		Vermiculite:				
Amosite:		Biotite:				
Crocidolite:		Mica:				
Anthophyllite:		Perlite:	-			
Tremolite:		Aggregates:				
Actinolite:		Styrofoam:				
NON-ASBESTOS FIE	ERS	OTHERS				
Synthetics:	2	Aluminum:				
Mineral Wool:		Bitumen:	50			
Fiberglass:		Resilient Material:				
Cellulose:	1	Glue:				
Animal Hair:		Binders:	47			
Antigorite:						

COMMENTS:

It is certified by the signatures below that the laboratory identified is accredited by the National Institute of Standards and Technology for Polarized Light Microscopy (PLM) analysis under the EPA Interim Asbestos Bulk Sample Quality Assurance Program, Laboratory 102082-0.

Microanalyst:

Svetlana Arkhipov

et hipoc

QCAnalyst

Andrew Pittman



3125 Marjan Drive Atlanta, GA 30340 Tel: (770) 457-8177 Fax: (770) 457-8188 AES Job Number: B212 Page 183 of 183 Total Samples Thursday, February 10, 2000



BULK SAMPLE ANALYSIS

Client Name:

BAT Associates, Inc.

Project Name:

Charleston Naval Shipyard

Project Number

971001

Client Sample ID:

34-19-3

AES Lab ID:

3553

Location:

Not given

Sample Description: Black semi-hard bitumenous to silty with fibers.

All percer	ntages g	iven below are visually estimated by volume	
ASBESTOS FIBEI	RS	NON-FIBROUS MAT	ERIALS
Chrysotile:		Vermiculite:	_
Amosite:		Biotite:	
Crocidolite:		Mica:	
Anthophyllite:		Perlite:	
Tremolite:		Aggregates:	
Actinolite:		Styrofoam:	
NON-ASBESTOS FIE	BERS	OTHERS	
Synthetics:	2	Aluminum:	
Mineral Wool:		Bitumen:	50
Fiberglass:		Resilient Material:	.
Cellulose:	1	Glue:	
Animal Hair:		Binders:	47
Antigorite:		- 1	

COMMENTS:

It is certified by the signatures below that the laboratory identified is accredited by the National Institute of Standards and Technology for Polarized Light Microscopy (PLM) analysis under the EPA Interim Asbestos Bulk Sample Quality Assurance Program, Laboratory 102082-0.


Microanalyst:

Svetlana Arkhipov

Shipoo

QCAnalyst

Andrew Pittman



2302 PARKLAKE DRIVE, SUITE 200, ATLANTA, GA 30345 TEL: (770) 908-7200 FAX: (770) 908-7219

ACCREDITED

LAB CODE - 102111

POLARIZED LIGHT MICROSCOPY (PLM) BULK SAMPLE ANALYSIS REPORT

CLIENT NAME:	BAT ASSOCIATES	LAB JOB NO:	B9334-2			
PROJECT NAME:	CHARLESTON NSY / 971001-13.03	DATE RECEIVED:	12/16/99			
PROJECT NO:	L802Z.000	REPORT ISSUED:	1/13/00			
0.1.15) = 515) 5 15		LADID	000074			
SAMPLE FIELD ID:	31-6-1	LAB ID:	928074			
SAMPLE INFO:		DATE ANALYZED:	1/10/00			
	SAMPLE DESCRIPTION	l				
LAYERED: NO						
APPEARANCE: GRAY SOFT FIBROUS TO GRANULAR TO POWDERY WITH PAINT						
			·			

RESULT OF ANALYSIS IN VOLUME PERCENTAGE (BY VISUAL ESTIMATE)

ASBESTOS FIBERS	NONASBESTOS FIBERS		NONFIBROUS COMPONENTS		OTHER COMPONENTS	
CHRYSOTILE	CELLULOSE	30	VERMICULITE/MICA		BITUMEN/TAR	T
AMOSITE	GLASS FIBERS	30	PERLITE	30	SAND/AGGR.	
CROCIDOLITE	SYNTHETICS		EXPANDED GLASS		GLUE/CAULK	
TREMOLITE	WOLLASTONITE		SYNTHETIC FOAM		VINYL	
ACTINOLITE	TALC		ALUMINUM/METAL		CORK	
ANTHOPHYLLITE			FOAM RUBBER		LATEX/RUBBER	
					PAINT/OTHER	10

COMMENTS:

SAMPLE WAS ANALYZED BY PLM USING DISPERSION STAINING TECHNIQUES IN ACCORDANCE WITH U.S. EPA
METHOD 40CFR Ch. I (7-1-92) PT. 763, SUBPT. F, APP. A. LAST CALIBRATION OF EQUIPMENT WAS PERFORMED ON: 1/10/00
FOR ALL HETEROGENEOUS AND LAYERED SAMPLES EASILY SEPARATED INTO SUBLAYERS, EACH LAYER IS ANALYZED SEPARATELY.
REPORT 1 OF 1


ANALYST

STEVE JARVI

ÓNT/ROL

ALEKSEY REZNIK

PLM IS NOT CONSISTENTLY RELIABLE IN DETECTING SMALL CONCENTRATION OF ASBESTOS IN FLOOR TILES AND SIMILAR NONFRIABLE MATERIALS, QUANTITATIVE TEM IS CURRENTLY THE ONLY METHOD THAT CAN BE USED TO GET THE CONCLUSIVE ASBESTOS CONTENT. THIS REPORT RELATES ONLY TO THE ITEMS TESTED. THIS REPORT SHALL NOT BE REPRODUCED EXCEPT IN FULL, AND NOT WITHOUT WRITTEN APPROVAL OF THE LABORATORY, THIS REPORT SHALL NOT BE USED TO CLAIM ENDORSEMENT BY WILAP OR ANY AGENCY OF U.S.). SOVERMENT.



2302 PARKLAKE DRIVE, SUITE 200, ATLANTA, GA 30345 TEL: (770) 908-7200 FAX: (770) 908-7219 MATVD ®

ACCREDITED

LAB CODE - 102111

POLARIZED LIGHT MICROSCOPY (PLM) BULK SAMPLE ANALYSIS REPORT

CLIENT NAME:	IENT NAME: BAT ASSOCIATES		B9334-2
PROJECT NAME:	CHARLESTON NSY / 971001-13.03	DATE RECEIVED:	12/16/99
PROJECT NO:	L802Z.000	REPORT ISSUED:	1/13/00
		,	
SAMPLE FIELD ID:	31-6-2	LAB ID:	928075
SAMPLE INFO:		DATE ANALYZED:	1/10/00
	SAMPLE DESCRIPTION	1	
LAYERED: NO			
APPEARANCE:	GRAY SOFT FIBROUS TO GRANULAR TO POW	DERY WITH PAINT	

RESULT OF ANALYSIS IN VOLUME PERCENTAGE (BY VISUAL ESTIMATE)

ASBESTOS FIBERS	NONASBESTOS F	NONASBESTOS FIBERS		NONFIBROUS COMPONENTS		OTHER COMPONENTS	
CHRYSOTILE	CELLULOSE	30	VERMICULITE/MICA	!	BITUMEN/TAR		
AMOSITE	GLASS FIBERS	30	PERLITE	25	SAND/AGGR.		
CROCIDOLITE	SYNTHETICS		EXPANDED GLASS		GLUE/CAULK		
TREMOLITE	WOLLASTONITE		SYNTHETIC FOAM	ı	VINYL		
ACTINOLITE	TALC		ALUMINUM/METAL		CORK		
ANTHOPHYLLITE			FOAM RUBBER	!	LATEX/RUBBER		
				!	PAINT/OTHER	15	

COMMENTS:

SAMPLE WAS ANALYZED BY PLM USING DISPERSION STAINING TECHNIQUES IN ACCORDANCE WITH U.S. EPA
METHOD 40CFR Ch. I (7-1-92) PT. 763, SUBPT. F, APP. A. LAST CALIBRATION OF EQUIPMENT WAS PERFORMED ON: 1/10/00
FOR ALL HETEROGENEOUS AND LAYERED SAMPLES EASILY SEPARATED INTO SUBLAYERS, EACH LAYER IS ANALYZED SEPARATELY.
REPORT 1 OF 1


ANALYST

ALEKSEY REZNIK

har

8TEVE JARVIS

PLM IS NOT CONSISTENTLY RELIABLE IN DETECTING SMALL CONCENTRATION OF ASBESTOS IN FLOOR TILES AND SIMILAR NOW FRIABLE MATERIALS, QUANTITATIVE TEM IS CURRENTLY THE ONLY METHOD THAT CAN BE USED TO GET THE CONCLUSIVE ASBESTOS CONTENT. THIS REPORT SHALL NOT BE REPORDUCED EXCEPT IN FULL, AND NOT WITHOUT WRITTEN APPROVAL OF THE LABORATORY. THIS REPORT SHALL NOT BE USED TO CLAIM ENDORSEMENT BY NYLAP OR ANY AGENCY OF U.S. GOVERMENT.



2302 PARKLAKE DRIVE, SUITE 200, ATLANTA, GA 30345 TEL: (770) 908-7200 FAX: (770) 908-7219

ACCREDITED

LAB CODE - 102111

POLARIZED LIGHT MICROSCOPY (PLM) **BULK SAMPLE ANALYSIS REPORT**

CLIENT NAME:	ENT NAME: BAT ASSOCIATES		B9334-2				
PROJECT NAME:	CHARLESTON NSY / 971001-13.03	DATE RECEIVED:	12/16/99				
PROJECT NO:	L802Z.000	REPORT ISSUED:	1/13/00				
SAMPLE FIELD ID:	31-6-3	LAB ID:	928076				
SAMPLE INFO:		DATE ANALYZED:	1/10/00				
	SAMPLE DESCRIPTION	١					
LAYERED: NO							
APPEARANCE: GRAY SOFT FIBROUS TO GRANULAR TO POWDERY WITH PAINT							
		A ho					

RESULT OF ANALYSIS IN VOLUME PERCENTAGE (BY VISUAL ESTIMATE)

ASBESTOS FIBERS	NONASBESTOS F	NONASBESTOS FIBERS		NONFIBROUS COMPONENTS		OTHER COMPONENTS	
CHRYSOTILE	CELLULOSE	25	VERMICULITE/MICA		BITUMEN/TAR		
AMOSITE	GLASS FIBERS	25	PERLITE	35	SAND/AGGR.		
CROCIDOLITE	SYNTHETICS		EXPANDED GLASS		GLUE/CAULK		
TREMOLITE	WOLLASTONITE		SYNTHETIC FOAM		VINYL		
ACTINOLITE	TALC		ALUMINUM/METAL		CORK		
ANTHOPHYLLITE			FOAM RUBBER	1	LATEX/RUBBER		
			-		PAINT/OTHER	15	

COMMENTS:


SAMPLE WAS ANALYZED BY PLM USING DISPERSION STAINING TECHNIQUES IN ACCORDANCE WITH U.S. EPA METHOD 40CFR Ch. I (7-1-92) PT. 763, SUBPT. F, APP. A. LAST CALIBRATION OF EQUIPMENT WAS PERFORMED ON: 1/10/00 FOR ALL HETEROGENEOUS AND LAYERED SAMPLES EASILY SEPARATED INTO SUBLAYERS, EACH LAYER IS ANALYZED SEPARATELY. REPORT 1 OF 1

ANALYST

ALEKSEY REZNIK

STEVE JARVIS

PLM IS NOT CONSISTENTLY RELIABLE IN DETECTING SMALL CONCENTRATION OF ASBESTOS IN FLOOR TILES AND SIMILAR NON FRIABLE MATERIALS, QUANTITATIVE TEM IS CURRENTLY THE ONLY METHOD THAT CAN BE USED TO GET THE CONCLUSIVE ASBESTOS CONTENT. THIS REPORT RELATES ONLY TO THE ITEMS TESTED. THIS REPORT SHALL NOT BE REPRODUCED EXCEPT IN FULL, AND NOT WITHOUT WRITTEN APPROVAL OF THE LABORATORY. THIS REPORT SHALL NOT BE USED TO CLAIM ENDORSEMENT BY NVLAP OR ANY AGENCY OF U.S. GOVERNENT.



P QAJVN

ACCREDITED

LAB CODE - 102111

POLARIZED LIGHT MICROSCOPY (PLM) BULK SAMPLE ANALYSIS REPORT

CLIENT NAME:	BAT ASSOCIATES	LAB JOB NO:	B9334-2
PROJECT NAME:	CHARLESTON NSY / 971001-13.03	DATE RECEIVED:	12/16/99
PROJECT NO:	L802Z.000	REPORT ISSUED:	1/13/00
SAMPLE FIELD ID:	31-7-1	LAB ID:	928077
SAMPLE INFO:		DATE ANALYZED:	1/10/00
	SAMPLE DESCRIPTIO	N	
LAYERED: NO			
APPEARANCE:	GRAY SOFT FIBROUS TO GRANULAR TO PO	WDERY WITH PAINT	

RESULT OF ANALYSIS IN VOLUME PERCENTAGE (BY VISUAL ESTIMATE)

ASBESTOS FIBERS	NONASBESTOS FIBERS		NONFIBROUS COMPONENTS		OTHER COMPONENTS	
CHRYSOTILE	CELLULOSE	35	VERMICULITE/MICA	T	BITUMEN/TAR	[
AMOSITE	GLASS FIBERS	25	PERLITE	30	SAND/AGGR.	
CROCIDOLITE	SYNTHETICS		EXPANDED GLASS	1	GLUE/CAULK	
TREMOLITE	WOLLASTONITE		SYNTHETIC FOAM		VINYL	ļ
ACTINOLITE	TALC		ALUMINUM/METAL		CORK	
ANTHOPHYLLITE			FOAM RUBBER	T	LATEX/RUBBER	
	_			İ	PAINT/OTHER	10


COMMENTS:

SAMPLE WAS ANALYZED BY PLM USING DISPERSION STAINING TECHNIQUES IN ACCORDANCE WITH U.S. EPA
METHOD 40CFR Ch. I (7-1-92) PT. 763, SUBPT. F, APP. A. LAST CALIBRATION OF EQUIPMENT WAS PERFORMED ON: 1/10/00 FOR ALL HETEROGENEOUS AND LAYERED SAMPLES EASILY SEPARATED INTO SUBLAYERS, EACH LAYER IS ANALYZED SEPARATELY.
REPORT 1 OF 1

ANALYST

ALEKSEY REZNIK

PLM IS NOT CONSISTENTLY RELIABLE IN DETECTING SMALL CONCENTRATION OF ASBESTOS IN FLOOR TILES AND SIMILAR NONFRIABLE MATERIALS, QUANTIFATIVE TEM IS CURRENTLY THE ONLY METHOD THAT CAN BE USED TO GET THE CONCLUSIVE ASBESTOS CONTENT. THIS REPORT RELATES ONLY TO THE ITEMS TESTED. THIS REPORT SHALL NOT BE REPORDUCED EXCEPT IN FULL. AND NOT WITHOUT WRITTEN APPROVAL OF THE LABORATORY. THIS REPORT SHALL NOT BE USED TO CLAIM ENDORSEMENT BY INVLAP OR ANY AGENCY OF U.S. GOVERMENT.



ACCREDITED

LAB CODE - 102111

POLARIZED LIGHT MICROSCOPY (PLM) BULK SAMPLE ANALYSIS REPORT

CLIENT NAME:	BATASSOCIATES	LAB JOB NO:	B9334-2
PROJECT NAME:	CHARLESTON NSY / 971001-13.03	DATE RECEIVED:	12/16/99
PROJECT NO:	L802Z.000	REPORT ISSUED:	1/13/00
SAMPLE FIELD ID:	31-7-2	LAB ID:	928078
SAMPLE INFO:		DATE ANALYZED:	1/10/00
	SAMPLE DESCRIPT	TION	
LAYERED: NO			
APPEARANCE:	GRAY SOFT FIBROUS TO GRANULAR TO P	POWDERY WITH PAINT	

RESULT OF ANALYSIS IN VOLUME PERCENTAGE (BY VISUAL ESTIMATE)

ASBESTOS FIBERS	ASBESTOS FIBERS NONASBESTOS FIBERS NONFIB		NONFIBROUS COMPO	NENTS	OTHER COMPONENTS	
CHRYSOTILE	CELLULOSE	35	VERMICULITE/MICA	Ι'	BITUMEN/TAR	
AMOSITE	GLASS FIBERS	25	PERLITE	30	SAND/AGGR.	†
CROCIDOLITE	SYNTHETICS		EXPANDED GLASS		GLUE/CAULK	1
TREMOLITE	WOLLASTONITE		SYNTHETIC FOAM		VINYL	
ACTINOLITE	TALC		ALUMINUM/METAL		CORK	
ANTHOPHYLLITE			FOAM RUBBER	1	LATEX/RUBBER	
				i	PAINT/OTHER	10

COMMENTS:


SAMPLE WAS ANALYZED BY PLM USING DISPERSION STAINING TECHNIQUES IN ACCORDANCE WITH U.S. EPA
METHOD 40CFR Ch. I (7-1-92) PT. 763, SUBPT. F, APP. A. LAST CALIBRATION OF EQUIPMENT WAS PERFORMED ON: 1/10/00
FOR ALL HETEROGENEOUS AND LAYERED SAMPLES EASILY SEPARATED INTO SUBLAYERS, EACH LAYER IS ANALYZED SEPARATELY.
REPORT 1 OF 1

ANALYST

- X

ALEKSEY REZNIK

PLM IS NOT CONSISTENTLY RELIABLE IN DETECTING SMALL CONCENTRATION OF ASSESTOS IN FLOOR TILES AND SIMILAR NOTIFICABLE MATERIALS, QUANTITATIVE TEM IS CURRENTLY THE ONLY METHOD THAT CAN BE USED TO GET THE CONCLUSIVE ASSESTOS CONTENT. THIS REPORT RELITES ONLY TO THE ITEMS TESTED. THIS REPORT SHALL NOT BE REPORDUCED EXCEPT IN FULL. AND NOT WITHOUT WRITTEN APPROVAL OF THE LABORATORY. THIS REPORT SHALL NOT BE USED TO CLAIM ENDORSEMENT BY INVAPOR ANY AGENCY OF U.S. GOVERNMENT.



ACCREDITED
LAB CODE - 102111

POLARIZED LIGHT MICROSCOPY (PLM) BULK SAMPLE ANALYSIS REPORT

CLIENT NAME:	BAT ASSOCIATES	LAB JOB NO:	B9334-2
PROJECT NAME:	CHARLESTON NSY / 971001-13.03	DATE RECEIVED:	12/16/99
PROJECT NO:	L802Z.000	REPORT ISSUED:	1/13/00
0			000070
SAMPLE FIELD ID:	31-7-3	LAB ID:	928079
SAMPLE INFO:		DATE ANALYZED:	1/10/00
	SAMPLE DESCRIPTION	J	
LAYERED: NO			
APPEARANCE:	GRAY SOFT FIBROUS TO GRANULAR TO POW	DERY WITH PAINT	

RESULT OF ANALYSIS IN VOLUME PERCENTAGE (BY VISUAL ESTIMATE)

ASBESTOS FIBERS	NONASBESTOS FIBERS		NONFIBROUS COMPONENTS		OTHER COMPONENTS	
CHRYSOTILE	CELLULOSE	30	VERMICULITE/MICA		BITUMEN/TAR	T
AMOSITE	GLASS FIBERS	30	PERLITE	30	SAND/AGGR.	
CROCIDOLITE	SYNTHETICS		EXPANDED GLASS		GLUE/CAULK	
TREMOLITE	WOLLASTONITE		SYNTHETIC FOAM		VINYL	
ACTINOLITE	TALC		ALUMINUM/METAL		CORK	
ANTHOPHYLLITE			FOAM RUBBER		LATEX/RUBBER	
					PAINT/OTHER	10

COMMENTS:


SAMPLE WAS ANALYZED BY PLM USING DISPERSION STAINING TECHNIQUES IN ACCORDANCE WITH U.S. EPA
METHOD 40CFR Ch. I (7-1-92) PT. 763, SUBPT. F, APP. A. LAST CALIBRATION OF EQUIPMENT WAS PERFORMED ON: 1/10/00
FOR ALL HETEROGENEOUS AND LAYERED SAMPLES EASILY SEPARATED INTO SUBLAYERS, EACH LAYER IS ANALYZED SEPARATELY.
REPORT 1 OF 1

ANALYST

ALEKSEY REZNIK

STEVE JARVIS

PLM IS NOT CONSISTENTLY RELIABLE IN DETECTING SMALL CONCENTRATION OF ASBESTOS IN FLOOR TILES AND SIMILAR NOTERIABLE MATERIALS, QUANTITATIVE TEM IS CURRENTLY THE ONLY METHOD THAT CAN BE USED TO GET THE CONCLUSIVE ASBESTOS CONTENT. THIS REPORT RELATES ONLY TO THE ITEMS TESTED. THIS REPORT SHALL NOT BE REPORDUCED EXCEPT IN FULL, AND NOT WITHOUT WRITTEN APPROVAL OF THE LABORATORY. THIS REPORT SHALL NOT BE USED TO CLAIM ENDORSEMENT BY INVLAP OR ANY AGENCY OF U.S. GOVERNMENT.



ACCREDITED

LAB CODE - 102111

POLARIZED LIGHT MICROSCOPY (PLM) **BULK SAMPLE ANALYSIS REPORT**

CLIENT NAME: BAT ASSOCIATES		LAB JOB NO:	B9334-1				
PROJECT NAME:	PROJECT NAME: CHARLESTON NSY / 971001-13.03		12/16/99				
PROJECT NO: L802Z.000		REPORT ISSUED:	1/13/00				
SAMPLE FIELD ID:	36-3-1	LAB ID:	928044				
SAMPLE INFO:		DATE ANALYZED:	1/7/00				
	SAMPLE DESCRIPTION	I					
LAYERED: NO							
APPEARANCE:	APPEARANCE: BLACK SOFT BITUMINOUS TO POWDERY WITH FIBERS						

RESULT OF ANALYSIS IN VOLUME PERCENTAGE (BY VISUAL ESTIMATE)

ASBESTOS FIBERS	NONASBESTOS FIBERS		NONFIBROUS COMPONENTS	OTHER COMPONENTS	
CHRYSOTILE	CELLULOSE	2	VERMICULITE/MICA	BITUMEN/TAR	80
AMOSITE	GLASS FIBERS		PERLITE	SAND/AGGR.	3
CROCIDOLITE	SYNTHETICS	2	EXPANDED GLASS	GLUE/CAULK	
TREMOLITE	WOLLASTONITE		SYNTHETIC FOAM	VINYL	
ACTINOLITE	TALC		ALUMINUM/METAL	CORK	1
ANTHOPHYLLITE			FOAM RUBBER	LATEX/RUBBER	
				PAINT/OTHER	13

COMMENTS:

SAMPLE WAS ANALYZED BY PLM USING DISPERSION STAINING TECHNIQUES IN ACCORDANCE WITH U.S. EPA METHOD 40CFR Ch. I (7-1-92) PT. 763, SUBPT. F, APP. A. LAST CALIBRATION OF EQUIPMENT WAS PERFORMED ON: 1/7/00 FOR ALL HETEROGENEOUS AND LAYERED SAMPLES EASILY SEPARATED INTO SUBLAYERS, EACH LAYER IS ANALYZED SEPARATELY. REPORT 1 OF 1

ANALYST


ALEKSEY REZNIK

nne

STEVE JÄRVIS

QUALITY

PLM IS NOT CONSISTENTLY RELIABLE IN DETECTING SMALL CONCENTRATION OF ASBESTOS IN FLOOR TILES AND SIMILAR NONFRABLE MATERIALS, QUANTITATIVE TEM IS CURRENTLY THE ONLY METHOD THAT CAN BE USED TO GET THE CONCLUSIVE ASBESTOS CONTENT. THIS REPORT RELATES ONLY TO THE ITEMS TESTED. THIS REPORT SHALL NOT BE REPRODUCED EXCEPT IN FULL, AND NOT WITHOUT WRITTEN APPROVAL OF THE LABORATORY. THIS REPORT SHALL NOT BE USED TO CLAIM ENDORSEMENT BY NYLAP OR ANY AGENCY OF U.S. GOVERNENT.



אלאט ®

ACCREDITED

LAB CODE - 102111

POLARIZED LIGHT MICROSCOPY (PLM) BULK SAMPLE ANALYSIS REPORT

CLIENT NAME:	BAT ASSOCIATES	LAB JOB NO:	B9334-1		
PROJECT NAME:	CHARLESTON NSY / 971001-13.03	DATE RECEIVED:	12/16/99		
PROJECT NO:	L802Z.000	REPORT ISSUED:	1/13/00		
SAMPLE FIELD ID:	36-3-2	LAB ID:	928045		
SAMPLE INFO:		DATE ANALYZED:	1/7/00		
	SAMPLE DESCRIPTI	ION			
LAYERED: NO	100				
APPEARANCE: BLACK SOFT BITUMINOUS TO POWDERY WITH FIBERS					

RESULT OF ANALYSIS IN VOLUME PERCENTAGE (BY VISUAL ESTIMATE)

ASBESTOS FIBERS	NONASBESTOS FIBERS		NONFIBROUS COMPONENTS	OTHER COMPONENTS	
CHRYSOTILE	CELLULOSE	2	VERMICULITE/MICA	BITUMEN/TAR	80
AMOSITE	GLASS FIBERS		PERLITE	SAND/AGGR.	3
CROCIDOLITE	SYNTHETICS	3	EXPANDED GLASS	GLUE/CAULK	
TREMOLITE	WOLLASTONITE		SYNTHETIC FOAM	VINYL	
ACTINOLITE	TALC		ALUMINUM/METAL	CORK	
ANTHOPHYLLITE			FOAM RUBBER	LATEX/RUBBER	
				PAINT/OTHER	12

COMMENTS:

SAMPLE WAS ANALYZED BY PLM USING DISPERSION STAINING TECHNIQUES IN ACCORDANCE WITH U.S. EPA
METHOD 40CFR Ch. I (7-1-92) PT. 763, SUBPT. F, APP. A. LAST CALIBRATION OF EQUIPMENT WAS PERFORMED ON: 1/7/00
FOR ALL HETEROGENEOUS AND LAYERED SAMPLES EASILY SEPARATED INTO SUBLAYERS, EACH LAYER IS ANALYZED SEPARATELY.
REPORT 1 OF 1


ANALYST

QUALITY/CONTROI

ALEKSEY REZNIK

STEVE JARVIS

PLM IS NOT CONSISTENTLY RELIABLE IN DETECTING SMALL CONCENTRATION OF ASBESTOS IN FLOOR TILES AND SIMILAR NON-FRABLE MATERIALS, QUANTITATIVE TEM IS CURRENTLY THE ONLY METHOD THAT CAN BE USED TO GET THE CONCLUSIVE ASBESTOS CONTENT. THIS REPORT RELATES ONLY TO THE ITEMS TESTED. THIS REPORT SHALL NOT BE REPRODUCED EXCEPT IN FULL, AND NOT WITHOUT WRITTEN APPROVAL OF THE LABORATORY. THIS REPORT SHALL NOT BE USED TO CLAIM ENCORSEMENT BY MYLAP OR ANY AGENCY OF U.S. GOVERNMENT.



2302 PARKLAKE DRIVE, SUITE 200, ATLANTA, GA 30345 FAX: (770) 908-7219 TEL: (770) 908-7200

ACCREDITED

LAB CODE - 102111

POLARIZED LIGHT MICROSCOPY (PLM) **BULK SAMPLE ANALYSIS REPORT**

CLIENT NAME:	BAT ASSOCIATES	LAB JOB NO:	B9334-1			
PROJECT NAME:	CHARLESTON NSY / 971001-13.03	DATE RECEIVED:	12/16/99			
PROJECT NO:	L802Z.000	REPORT ISSUED:	1/13/00			
SAMPLE FIELD ID:	36-3-3	LAB ID:	928046			
SAMPLE INFO:		DATE ANALYZED:	1/7/00			
	SAMPLE DESCRIPTION	1	_			
LAYERED: NO			10000			
APPEARANCE:	APPEARANCE: BLACK SOFT BITUMINOUS TO POWDERY WITH FIBERS					
		THE RESERVE OF THE PERSON OF T				

RESULT OF ANALYSIS IN VOLUME PERCENTAGE (BY VISUAL ESTIMATE)

ASBESTOS FIBERS	NONASBESTOS FI	BERS	NONFIBROUS COMPONENT	OTHER COMPO	OTHER COMPONENTS	
CHRYSOTILE	CELLULOSE	2	VERMICULITE/MICA	BITUMEN/TAR	80	
AMOSITE	GLASS FIBERS		PERLITE	SAND/AGGR.	2	
CROCIDOLITE	SYNTHETICS	3	EXPANDED GLASS	GLUE/CAULK		
TREMOLITE	WOLLASTONITE		SYNTHETIC FOAM	VINYL		
ACTINOLITE	TALC		ALUMINUM/METAL	CORK	1	
ANTHOPHYLLITE			FOAM RUBBER	LATEX/RUBBER		
				PAINT/OTHER	13	

COMMENTS:

SAMPLE WAS ANALYZED BY PLM USING DISPERSION STAINING TECHNIQUES IN ACCORDANCE WITH U.S. EPA METHOD 40CFR Ch. I (7-1-92) PT. 763, SUBPT. F, APP. A. LAST CALIBRATION OF EQUIPMENT WAS PERFORMED ON: 1/7/00 FOR ALL HETEROGENEOUS AND LAYERED SAMPLES EASILY SEPARATED INTO SUBLAYERS, EACH LAYER IS ANALYZED SEPARATELY. REPORT 1 OF 1

ANALYST


ŔOL

QUALITY

ALEKSEY REZNIK

STEVE JARVIS

PLM IS NOT CONSISTENTLY RELIABLE IN DETECTING SMALL CONCENTRATION OF ASBESTOS IN FLOOR TILES AND SIMILAR NON-RIABLE MATERIALS, QUANTITATIVE TEM IS CURRENTLY THE ONLY METHOD THAT CAN BE USED TO GET THE CONCLUSIVE ASBESTOS CONTENT. THIS REPORT RELATES ONLY TO THE TIEMS TESTED. THIS REPORT SHALL NOT BE REPORD EXCEPT IN FULL, AND NOT WITHOUT WRITTEN APPROVAL OF THE LABORATORY. THIS REPORT SHALL NOT BE USED TO CLAIM ENDORSEMENT BY NOLAP OR ANY AGENCY OF U.S. GOVERNMENT.



ACCREDITED

LAB CODE - 102111

POLARIZED LIGHT MICROSCOPY (PLM) BULK SAMPLE ANALYSIS REPORT

CLIENT NAME:	BAT ASSOCIATES	LAB JOB NO:	B9334-1
PROJECT NAME:	CHARLESTON NSY / 971001-13.03	DATE RECEIVED:	12/16/99
PROJECT NO:	L802Z.000	REPORT ISSUED:	1/13/00
	•		
SAMPLE FIELD ID:	36-4-1	LAB ID:	928047
SAMPLE INFO:		DATE ANALYZED:	1/7/00
	SAMPLE DESCRIPTION	1	
LAYERED: NO			
APPEARANCE:	GRAY HARD SILTY		

RESULT OF ANALYSIS IN VOLUME PERCENTAGE (BY VISUAL ESTIMATE)

ASBESTOS FIBERS	NONASBESTOS FIBERS	NONFIBROUS COMPONENTS	OTHER COMPONENTS	
CHRYSOTILE	CELLULOSE	VERMICULITE/MICA	BITUMEN/TAR	_
AMOSITE	GLASS FIBERS	PERLITE	SAND/AGGR.	5
CROCIDOLITE	SYNTHETICS	EXPANDED GLASS	GLUE/CAULK	
TREMOLITE	WOLLASTONITE	SYNTHETIC FOAM	VINYL	
ACTINOLITE	TALC	ALUMINUM/METAL	CORK	
ANTHOPHYLLITE		FOAM RUBBER	LATEX/RUBBER	
			PAINT/OTHER	95

COMMENTS:

SAMPLE WAS ANALYZED BY PLM USING DISPERSION STAINING TECHNIQUES IN ACCORDANCE WITH U.S. EPA METHOD 40CFR Ch. I (7-1-92) PT. 763, SUBPT. F, APP. A. LAST CALIBRATION OF EQUIPMENT WAS PERFORMED ON: 1/7/00 FOR ALL HETEROGENEOUS AND LAYERED SAMPLES EASILY SEPARATED INTO SUBLAYERS, EACH LAYER IS ANALYZED SEPARATELY. REPORT 1 OF 1

ANALYST

ALEKSEY REZNIK

ann

STEVE JARVIS

ROL

QUALITX

PLM IS NOT CONSISTENTLY RELIABLE IN DETECTING SMALL CONCENTRATION OF ASBESTOS IN FLOOR TILES AND SIMILAR NON PRIBALE MATERIALS, QUANTITATIVE TEM IS CURRENTLY THE ONLY METHOD THAT CAN BE USED TO GET THE CONCLUSIVE ASBESTOS CONTENT. THIS REPORT RELATES ONLY TO THE ITEMS TESTED. THIS REPORT SHALL NOT BE REPORDOUCED EXCEPT IN FULL. AND NOT WITHOUT WRITTEN APPROVAL OF THE LABORATORY, THIS REPORT SHALL NOT BE USED TO CLAIM ENDORSEMENT BY NYLAP OR ANY AGENCY OF U.S. GOVERMENT.



ACCREDITED
LAB CODE - 102111

POLARIZED LIGHT MICROSCOPY (PLM) BULK SAMPLE ANALYSIS REPORT

CLIENT NAME:	BAT ASSOCIATES		B9334-1
PROJECT NAME:	CHARLESTON NSY / 971001-13.03	DATE RECEIVED:	12/16/99
PROJECT NO:	L802Z.000	REPORT ISSUED:	1/13/00
SAMPLE FIELD ID:	36-4-2	LAB ID:	928048
SAMPLE INFO:		DATE ANALYZED:	1/7/00
	SAMPLE DE	SCRIPTION	
LAYERED: NO			
APPEARANCE:	GRAY HARD SILTY		

RESULT OF ANALYSIS IN VOLUME PERCENTAGE (BY VISUAL ESTIMATE)

ASBESTOS FIBERS	NONASBESTOS FIBERS	NONFIBROUS COMPONENTS	OTHER COMPONENTS	
CHRYSOTILE	CELLULOSE	VERMICULITE/MICA	BITUMEN/TAR	
AMOSITE	GLASS FIBERS	PERLITE	SAND/AGGR.	7
CROCIDOLITE	SYNTHETICS	EXPANDED GLASS	GLUE/CAULK	
TREMOLITE	WOLLASTONITE	SYNTHETIC FOAM	VINYL	
ACTINOLITE	TALC	ALUMINUM/METAL	CORK	
ANTHOPHYLLITE		FOAM RUBBER	LATEX/RUBBER	
			PAINT/OTHER	93

COMMENTS:

SAMPLE WAS ANALYZED BY PLM USING DISPERSION STAINING TECHNIQUES IN ACCORDANCE WITH U.S. EPA METHOD 40CFR Ch. I (7-1-92) PT. 763, SUBPT. F, APP. A. LAST CALIBRATION OF EQUIPMENT WAS PERFORMED ON: 1/7/00 FOR ALL HETEROGENEOUS AND LAYERED SAMPLES EASILY SEPARATED INTO SUBLAYERS, EACH LAYER IS ANALYZED SEPARATELY. REPORT 1 OF 1

ANALYST

STEVE JARVIS

ALEKSEY REZNIK

PLM IS NOT CONSISTENTLY RELIABLE IN DETECTING SMALL CONCENTRATION OF ASSESTOS IN FLOOR TILES AND SIMILAR NOT PRIABLE MATERIALS, QUANTITATIVE TEM IS CURRENTLY THE ONLY METHOD THAT CAN BE USED TO GET THE CONCLUSIVE ASSESTOS CONTENT. THIS REPORT RELATES ONLY TO THE ITEMS TESTED. THIS REPORT SHALL NOT BE REPORDUCED EXCEPT IN FULL, AND NOT WITHOUT WRITTEN APPROVAL OF THE LABORATORY. THIS REPORT SHALL NOT BE USED TO CLAIM ENDORSEMENT BY NYLAP OR ANY AGENCY OF U.S. GOVERNMENT.



ACCREDITED

LAB CODE - 102111

POLARIZED LIGHT MICROSCOPY (PLM) **BULK SAMPLE ANALYSIS REPORT**

CLIENT NAME:	BAT ASSOCIATES	LAB JOB NO:	B9334-1
PROJECT NAME:	CHARLESTON NSY / 971001-13.03	DATE RECEIVED:	12/16/99
PROJECT NO:	L802Z.000	REPORT ISSUED:	1/13/00
SAMPLE FIELD ID:	36-4-3	LAB ID:	928049
SAMPLE INFO:		DATE ANALYZED:	1/7/00
	SAMPLE DESCRIPTION	N	
LAYERED: NO			
APPEARANCE:	GRAY HARD SILTY		

RESULT OF ANALYSIS IN VOLUME PERCENTAGE (BY VISUAL ESTIMATE)

ASBESTOS FIBERS	NONASBESTOS FIBERS	SBESTOS FIBERS NONFIBROUS COMPONENTS OTHER COMPONI		ENTS
CHRYSOTILE	CELLULOSE	VERMICULITE/MICA	BITUMEN/TAR	
AMOSITE	GLASS FIBERS	PERLITE	SAND/AGGR.	5
CROCIDOLITE	SYNTHETICS	EXPANDED GLASS	GLUE/CAULK	
TREMOLITE	WOLLASTONITE	SYNTHETIC FOAM	VINYL	
ACTINOLITE	TALC	ALUMINUM/METAL	CORK	
ANTHOPHYLLITE		FOAM RUBBER	LATEX/RUBBER	
			PAINT/OTHER	95

COMMENTS:

SAMPLE WAS ANALYZED BY PLM USING DISPERSION STAINING TECHNIQUES IN ACCORDANCE WITH U.S. EPA METHOD 40CFR Ch. I (7-1-92) PT. 763, SUBPT. F, APP. A. LAST CALIBRATION OF EQUIPMENT WAS PERFORMED ON: 1/7/00 FOR ALL HETEROGENEOUS AND LAYERED SAMPLES EASILY SEPARATED INTO SUBLAYERS, EACH LAYER IS MANALYZED SEPARATELY. REPORT 1 OF 1


ANALYST

STEVĚ JARVIS

T/ROL

ALEKSEY REZNIK

PLM IS NOT CONSISTENTLY RELIABLE IN DETECTING SMALL CONCENTRATION OF ASBESTOS IN FLOOR TILES AND SMILAR NON-FRIABLE MATERIALS, QUANTITATIVE TEM IS CURRENTLY THE ONLY METHOD THAT CAN BE USED TO GET THE CONCLUSIVE ASBESTOS CONTENT. THIS REPORT RELATES ONLY TO THE ITEMS TESTED. THIS REPORT SHALL NOT BE REPRODUCED EXCEPT IN FULL. AND NOT WITHOUT WRITTEN APPROVAL OF THE LABORATORY. THIS REPORT SHALL NOT BE USED TO CLAIM ENDORSEMENT BY MYLAP OR ANY AGENCY OF U.S. GOVERNENT.



NYLAP ®
ACCREDITED

ACCREDITED

LAB CODE - 102111

POLARIZED LIGHT MICROSCOPY (PLM) BULK SAMPLE ANALYSIS REPORT

CLIENT NAME:	BAT ASSOCIATES	LAB JOB NO:	B9334-2
PROJECT NAME:	CHARLESTON NSY / 971001-13.03	DATE RECEIVED:	12/16/99
PROJECT NO:	L802Z.000	REPORT ISSUED:	1/13/00
SAMPLE FIELD ID:	33-3-1	LAB ID:	928056
SAMPLE INFO:		DATE ANALYZED:	1/10/00
	SAMPLE DESCRI	PTION	
LAYERED: NO			
APPEARANCE:	WHITE SOFT POWDERY TO FIBROUS WI	TH CANVAS AND PAINT	

RESULT OF ANALYSIS IN VOLUME PERCENTAGE (BY VISUAL ESTIMATE)

ASBESTOS FIB	ERS	NONASBESTOS FI	BERS	NONFIBROUS COMPONENTS	OTHER COMPO	NENTS
CHRYSOTILE	15	CELLULOSE	20	VERMICULITE/MICA	BITUMEN/TAR	T
AMOSITE	15	GLASS FIBERS		PERLITE	SAND/AGGR.	
CROCIDOLITE		SYNTHETICS		EXPANDED GLASS	GLUE/CAULK	
TREMOLITE		WOLLASTONITE		SYNTHETIC FOAM	VINYL	
ACTINOLITE		TALC		ALUMINUM/METAL	CORK	
ANTHOPHYLLITE				FOAM RUBBER	LATEX/RUBBER	
					PAINT/OTHER	50

COMMENTS:

SAMPLE WAS ANALYZED BY PLM USING DISPERSION STAINING TECHNIQUES IN ACCORDANCE WITH U.S. EPA
METHOD 40CFR Ch. I (7-1-92) PT. 763, SUBPT. F, APP. A. LAST CALIBRATION OF EQUIPMENT WAS PERFORMED ON: 1/10/00
FOR ALL HETEROGENEOUS AND LAYERED SAMPLES EASILY SEPARATED INTO SUBLAYERS, EACH LAYER IS ANALYZED SEPARATELY.
REPORT 1 OF 1


ANALYST

ALEKSEY REZNIK

STEVE JARVIS

RO

PLM IS NOT CONSISTENTLY RELIABLE IN DETECTING SMALL CONCENTRATION OF ASBESTOS IN FLOOR THES AND SIMILAR NON-RIABLE MATERIALS, QUANTITATIVE TEM IS CURRENTLY THE ONLY METHOD THAT CAN BE USED TO GET THE CONCLUSIVE ASSESTOS CONTEMT. THIS REPORT RELATES ONLY TO THE ITEMS TESTED. THIS REPORT SHALL NOT BE REPROQUED EXCEPT IN FULL, AND NOT WITHOUT WRITTEN APPROVAL OF THE LABORATORY. THIS REPORT SHALL NOT BE USED TO CLAIM ENDORSEMENT BY NYLAP OR ANY AGENCY OF U.S. GOVERMENT.



NATVD ®

ACCREDITED

LAB CODE - 102111

POLARIZED LIGHT MICROSCOPY (PLM) BULK SAMPLE ANALYSIS REPORT

CLIENT NAME:	BAT ASSOCIATES	LAB JOB NO:	B9334-2
PROJECT NAME:	CHARLESTON NSY / 971001-13.03	DATE RECEIVED:	12/16/99
PROJECT NO:	L802Z.000	REPORT ISSUED:	1/13/00
SAMPLE FIELD ID:	33-3-2	LAB ID:	928057
SAMPLE INFO:	00-0-2	DATE ANALYZED:	1/10/00
OAWI LE IVI O.			1710700
	SAMPLE DESCRIPTION	ON	
LAYERED: NO			
APPEARANCE:	WHITE SOFT POWDERY TO FIBROUS WITH	CANVAS AND PAINT	

RESULT OF ANALYSIS IN VOLUME PERCENTAGE (BY VISUAL ESTIMATE)

ASBESTOS FIBERS		NONASBESTOS FIBERS		NONFIBROUS COMPONENTS	OTHER COMPONENTS	
CHRYSOTILE	20	CELLULOSE	20	VERMICULITE/MICA	BITUMEN/TAR	
AMOSITE	15	GLASS FIBERS		PERLITE	SAND/AGGR.	
CROCIDOLITE		SYNTHETICS		EXPANDED GLASS	GLUE/CAULK	
TREMOLITE		WOLLASTONITE		SYNTHETIC FOAM	VINYL	
ACTINOLITE		TALC		ALUMINUM/METAL	CORK	
ANTHOPHYLLITE				FOAM RUBBER	LATEX/RUBBER	
			_		PAINT/OTHER	45

COMMENTS:


SAMPLE WAS ANALYZED BY PLM USING DISPERSION STAINING TECHNIQUES IN ACCORDANCE WITH U.S. EPA METHOD 40CFR Ch. I (7-1-92) PT. 763, SUBPT. F, APP. A. LAST CALIBRATION OF EQUIPMENT WAS PERFORMED ON: 1/10/00 FOR ALL HETEROGENEOUS AND LAYERED SAMPLES EASILY SEPARATED INTO SUBLAYERS, EACH LAYER IS ANALYZED SEPARATELY. REPORT 1 OF 1

ANALYST

ALEKSEY REZNIK

QUALITY/CONTRO

PLM IS NOT CONSISTENTLY RELIABLE IN DETECTING SMALL CONCENTRATION OF ASBESTOS IN FLOOR TILES AND SIMILAR NON-FIABLE MATERIALS, QUANTIFATIVE TEM IS CURRENTLY THE ONLY METHOD THAT CAN BE USED TO GET THE CONCLUSIVE ASBESTOS CONTENT. THIS REPORT RELATES ONLY TO THE ITEMS TESTED. THIS REPORT SHALL NOT BE REPRODUCED EXCEPT IN FULL, AND NOT WITHOUT WRITTEN APPROVAL OF THE LABORATORY. THIS REPORT SHALL NOT BE USED TO CLAIM ENDORSEMENT BY NYLAP OR ANY AGENCY OF U.S. GOVERNENT.



פלאלא 🖲

ACCREDITED
LAB CODE - 102111

POLARIZED LIGHT MICROSCOPY (PLM) BULK SAMPLE ANALYSIS REPORT

CLIENT NAME:	BAT ASSOCIATES	LAB JOB NO:	B9334-2
PROJECT NAME:	CHARLESTON NSY / 971001-13.03	DATE RECEIVED:	12/16/99
PROJECT NO:	L802Z.000	REPORT ISSUED:	1/13/00
SAMPLE FIELD ID:	33-3-3	LAB ID:	928058
SAMPLE INFO:		DATE ANALYZED:	1/10/00
	SAMPLE DESCRIPTION	l	
LAYERED: NO			_
APPEARANCE:	WHITE SOFT POWDERY TO FIBROUS WITH CA	ANVAS AND PAINT	

RESULT OF ANALYSIS IN VOLUME PERCENTAGE (BY VISUAL ESTIMATE)

ASBESTOS FIBERS		NONASBESTOS FI	ONASBESTOS FIBERS NONFIBROUS COMPONENTS		OTHER COMPONENTS	
CHRYSOTILE	20	CELLULOSE	15	VERMICULITE/MICA	BITUMEN/TAR	Ī
AMOSITE	20	GLASS FIBERS		PERLITE	SAND/AGGR.	
CROCIDOLITE		SYNTHETICS		EXPANDED GLASS	GLUE/CAULK	
TREMOLITE		WOLLASTONITE		SYNTHETIC FOAM	VINYL	Ī
ACTINOLITE		TALC		ALUMINUM/METAL	CORK	
ANTHOPHYLLITE				FOAM RUBBER	LATEX/RUBBER	
					PAINT/OTHER	45

COMMENTS:

SAMPLE WAS ANALYZED BY PLM USING DISPERSION STAINING TECHNIQUES IN ACCORDANCE WITH U.S. EPA
METHOD 40CFR Ch. I (7-1-92) PT. 763, SUBPT. F, APP. A. LAST CALIBRATION OF EQUIPMENT WAS PERFORMED ON: 1/10/00
FOR ALL HETEROGENEOUS AND LAYERED SAMPLES EASILY SEPARATED INTO SUBLAYERS, EACH LAYER IS ANALYZED SEPARATELY.
REPORT 1 OF 1

ANALYST

ALEKSEY REZNIK

STEVE JARVIS

PLM IS NOT CONSISTENTLY RELIABLE IN DETECTING SMALL CONCENTRATION OF ASSESTOS IN FLOOR TILES AND SIMILAR NONFRIABLE MATERIALS, QUANTITATIVE TEM IS CURRENTLY THE ONLY METHOD THAT CAN BE USED TO GET THE CONCLUSIVE ASSESTOS CONTINT. THIS REPORT RELIATES ONLY TO THE ITEMS TESTED. THIS REPORT SHALL NOT BE REPORDUCED EXCEPT IN FULL, AND NOT WITHOUT WRITTEN APPROVAL OF THE LABORATORY. THIS REPORT SHALL NOT BE USED TO CLAIM ENDORSEMENT BY NYLAP OR ANY AGENCY OF U.S. GOVERMENT.



3125 Marjan Drive Atlanta, GA 30340 Tel: (770) 457-8177

Fax: (770) 457-8188

AES Job Number: **B212**Page 47 of 183 Total Samples
Wednesday, February 09, 2000



BULK SAMPLE ANALYSIS

Client Name:

B A T Associates, Inc.

Project Name:

Charleston Naval Shipyard

Project Number

971001

Client Sample ID:

36-15-1

AES Lab ID:

3417

Location:

Not given

Sample Description: Layered: 1) Black semi-hard bitumenous; 2) Black semi-hard bitumenous to

fibrous; 3) Brown soft fibrous to perlitic.

All percentages given below are visually estimated by volume

ASBESTOS FIBERS		NON-FIBROUS MA	TERIALS
Chrysotile:		Vermiculite:	
Amosite:		Biotite:	
Crocidolite:		Mica:	
Anthophyllite:		Perlite:	5
Tremolite:		Aggregates:	
Actinolite:		Styrofoam:	
NON-ASBESTOS FIBERS		OTHERS	
Synthetics:		Aluminum:	
Mineral Wool:	5	Bitumen:	60
Fiberglass:		Resilient Material:	
Cellulose:	30	Glue:	
Animal Hair:		Binders:	
Antigorite:			

COMMENTS:

It is certified by the signatures below that the laboratory identified is accredited by the National Institute of Standards and Technology for Polarized Light Microscopy (PLM) analysis under the EPA Interim Asbestos Bulk Sample Quality Assurance Program, Laboratory 102082-0.

Microanalyst:

Abripo 5

QCAnalyst

Andrew Pittman

Svetlana Arkhipov



ANALYTICAL ENVIRONMENTAL SERVICES, INC. 3125 Marjan Drive

Atlanta, GA 30340 Tel: (770) 457-8177

Fax: (770) 457-8188

AES Job Number: **B212** Page 48 of 183 Total Samples Wednesday, February 09, 2000



BULK SAMPLE ANALYSIS

Client Name:

BAT Associates, Inc.

Project Name:

Charleston Naval Shipyard

Project Number

971001

Client Sample ID:

36-15-2

AES Lab ID:

3418

Location:

Not given

Sample Description: Layered: 1) Black semi-hard bitumenous; 2) Black semi-hard bitumenous to

fibrous; 3) Brown soft fibrous to perlitic.

All percentages given below are visually estimated by volume

ASBESTOS FIBERS		NON-FIBROUS MA	TERIAL
Chrysotile:		Vermiculite:	
Amosite:		Biotite:	
Crocidolite:		Mica:	
Anthophyllite:		Perlite:	5
Tremolite:		Aggregates:	
Actinolite:		Styrofoam:	
NON-ASBESTOS FIBERS		OTHERS	
Synthetics:		Aluminum:	
Mineral Wool:	5	Bitumen:	60
Fiberglass:		Resilient Material:	
Cellulose:	30	Glue:	
Animal Hair:		Binders:	
Antigorite:			

COMMENTS:

It is certified by the signatures below that the laboratory identified is accredited by the National Institute of Standards and Technology for Polarized Light Microscopy (PLM) analysis under the EPA Interim Asbestos Bulk Sample Quality Assurance Program, Laboratory 102082-0.

Microanalyst:

Shipos

Svetlana Arkhipov

QCAnalyst

Andrew Pittman



ANALYTICAL ENVIRONMENTAL SERVICES, INC. 3125 Marjan Drive

Atlanta, GA 30340 Tel: (770) 457-8177

Fax: (770) 457-8188

AES Job Number: B212 Page 49 of 183 Total Samples Wednesday, February 09, 2000



BULK SAMPLE ANALYSIS

Client Name:

BAT Associates, Inc.

Project Name:

Client Sample ID:

Charleston Naval Shipyard

36-15-3

Location:

Not given

Project Number

971001

AES Lab ID:

3419

Sample Description: Layered: 1) Black semi-hard bitumenous with aggregates; 2) Black semi-hard

bitumenous to fibrous.

All percentages given below are visually estimated by volume			
ASBESTOS FI	BERS	NON-FIBROUS MAT	ERIALS
Chrysotile:		Vermiculite:	
Amosite:		Biotite:	
Crocidolite:		Mica:	_
Anthophyllite:		Perlite:	-
Tremolite:		Aggregates:	10
Actinolite:		Styrofoam:	
NON-ASBESTOS	FIBERS	OTHERS	
Synthetics:		Aluminum:	
Mineral Wool:		Bitumen:	65
Fiberglass:		Resilient Material:	-
Cellulose:	25	Glue:	
Animal Hair:		Binders:	
Antigorite:			

COMMENTS:

It is certified by the signatures below that the laboratory identified is accredited by the National Institute of Standards and Technology for Polarized Light Microscopy (PLM) analysis under the EPA Interim Asbestos Bulk Sample Quality Assurance Program, Laboratory 102082-0.

Microanalyst:

lhi pos

Svetlana Arkhipov

QCAnalyst

Andrew Pittman



ANALYTICAL ENVIRONMENTAL SERVICES, INC. 3125 Marjan Drive

Atlanta, GA 30340 Tel: (770) 457-8177

Fax: (770) 457-8188

AES Job Number: B212 Page 23 of 183 Total Samples Wednesday, February 09, 2000



BULK SAMPLE ANALYSIS

Client Name:

BAT Associates, Inc.

Project Name:

Charleston Naval Shipyard

Project Number

971001

Client Sample ID:

Exterior Pipe - 32

AES Lab ID:

3393

Location:

Not given

Sample Description: Layered: 1) Light brown semi-hard fibrous with aluminum; 2) Gray soft powdery to

fibrous.

All percentages given below are visually estimated by volume

ASBESTOS FIBERS		NON-FIBROUS MA'I	ERIALS
Chrysotile:		Vermiculite:	_
Amosite:	15	Biotite:	
Crocidolite:		Mica:	
Anthophyllite:		Perlite:	
Tremolite:		Aggregates:	
Actinolite:		Styrofoam:	
NON-ASBESTOS FIBERS		OTHERS	
Synthetics:		Aluminum:	5
Mineral Wool:		Bitumen:	
Fiberglass:		Resilient Material:	
Cellulose:	5	Glue:	
Animal Hair:		Binders:	75
Antigorite:			

COMMENTS: Layer #2 contains 15% amosite. Layer #1 does not contain asbestos.

It is certified by the signatures below that the laboratory identified is accredited by the National Institute of Standards and Technology for Polarized Light Microscopy (PLM) analysis under the EPA Interim Asbestos Bulk Sample Quality Assurance Program, Laboratory 102082-0.

Microanalyst:

QCAnalyst:

Svetlana Arkhipov



3125 Marjan Drive Atlanta, GA 30340 Tel: (770) 457-8177

Fax: (770) 457-8188

AES Job Number: B212 Page 26 of 183 Total Samples Wednesday, February 09, 2000



BULK SAMPLE ANALYSIS

Client Name:

BAT Associates, Inc.

Project Name:

Charleston Naval Shipyard

Project Number

971001

Client Sample ID:

B31-S1

AES Lab ID:

3396

Location:

Not given

Sample Description: Layered: 1) Red semi-hard silty to woven; 2) Gray semi-hard silty to fibrous; 3)

Light gray semi-hard fibrous.

All percentages given below are visually estimated by volume			
ASBESTOS FIBERS		NON-FIBROUS MATE	ERIALS
Chrysotile:		Vermiculite:	
Amosite:		Biotite:	
Crocidolite:		Mica:	
Anthophyllite:		Perlite:	
Tremolite:	- "	Aggregates:	
Actinolite:		Styrofoam:	
NON-ASBESTO	S FIBERS	OTHERS	
Synthetics:		Aluminum:	
Mineral Wool:	2	Bitumen:	
Fiberglass:	95	Resilient Material:	
Cellulose:		Glue:	
Animal Hair:		Binders:	3
Antigorite:		L	

COMMENTS:

It is certified by the signatures below that the laboratory identified is accredited by the National Institute of Standards and Technology for Polarized Light Microscopy (PLM) analysis under the EPA Interim Asbestos Bulk Sample Quality Assurance Program, Laboratory 102082-0.

Microanalyst:

Svetlana Arkhipov

febripos

QCAnalyst

Svetlana Arkhipov



3125 Marjan Drive Atlanta, GA 30340 Tel: (770) 457-8177 Fax: (770) 457-8188

AES Job Number: **B212** Page 27 of 183 Total Samples Wednesday, February 09, 2000



BULK SAMPLE ANALYSIS

Client Name:

BAT Associates, Inc.

Project Name:

Charleston Naval Shipyard

Project Number

971001

Client Sample ID:

B31-S2

AES Lab ID:

3397

Location:

Not given

Sample Description: Layered: 1) Red semi-hard silty to woven; 2) Gray semi-hard silty to fibrous; 3)

Light gray semi-hard fibrous.

All percentages given below are visually estimated by volume

ASBESTOS FIBERS		NON-FIBROUS MA
Chrysotile:		Vermiculite:
Amosite:		Biotite:
Crocidolite:		Mica:
Anthophyllite:		Perlite:
Tremolite:		Aggregates:
Actinolite:		Styrofoam:
NON-ASBESTO	S FIBERS	OTHERS
	S FIBERS	OTHERS Aluminum:
Synthetics:	S FIBERS	
Synthetics: Mineral Wool:		Aluminum:
Synthetics: Mineral Wool: Fiberglass:	2	Aluminum: Bitumen:
NON-ASBESTOS Synthetics: Mineral Wool: Fiberglass: Cellulose: Animal Hair:	2	Aluminum: Bitumen: Resilient Material:

COMMENTS:

It is certified by the signatures below that the laboratory identified is accredited by the National Institute of Standards and Technology for Polarized Light Microscopy (PLM) analysis under the EPA Interim Asbestos Bulk Sample Quality Assurance Program, Laboratory 102082-0.

Microanalyst:

Svetlana Arkhipov

QCAnalyst:

Svetlana Arkhipov



3125 Marjan Drive Atlanta, GA 30340 Tel: (770) 457-8177

Fax: (770) 457-8188

AES Job Number: Page 28 of 183 Total Samples Wednesday, February 09, 2000



BULK SAMPLE ANALYSIS

Client Name:

B A T Associates, Inc.

Project Name: Client Sample ID: **Charleston Naval Shipyard**

B31-S3

Location:

Not given

Project Number

971001

AES Lab ID:

3398

Sample Description: Light gray soft powdery to fibrous.

All percentages given below are visually estimated by volume			
ASBESTOS FIBERS		NON-FIBROUS MAT	ERIALS
Chrysotile:		Vermiculite:	
Amosite:		Biotite:	
Crocidolite:		Mica:	
Anthophyllite:		Perlite:	_
Tremolite:		Aggregates:	
Actinolite:		Styrofoam:	
NON-ASBESTO	S FIBERS	OTHERS	
Synthetics:	5	Aluminum:	
Mineral Wool:		Bitumen:	
Fiberglass:		Resilient Material:	
Cellulose:	20	Glue:	
Animal Hair:		Binders:	75
Antigorite:			

COMMENTS:

It is certified by the signatures below that the laboratory identified is accredited by the National Institute of Standards and Technology for Polarized Light Microscopy (PLM) analysis under the EPA Interm Asbestos Bulk Sample Quality Assurance Program, Laboratory 102082-0.

Microanalyst:

Svetlana Arkhipov

QCAnalyst

Svetlana Arkhipov

BAT Associates, Inc.
ENVIRONMENTAL, HEALTH & SAFETY SERVICES

5151 Brook Hollow Pkwy., Suite 250 Norcross, GA 30071

Phone: (770) 242-39031 Fax: (770) 242-3912

CHAIN OF CUSTODY FORM

BAT PROJECT CONTACT DOUGLAS J. MILTON		
BAT JOB NAME Charleston Naval Shipyard	BAT JOB NO. 971001 TASK NO. 13.03	
ANALYSIS REQUESTED ■ PLM □ PCM □ A	AAS For Lead Content OTHER	
CHECK ONE: ROUTINE ROUTINE - FAX (HANDWRITT		
SAMPLE ID	SAMPLE ID	
1. 31-2-1	16. 31-12-1	
2. 31-2-2	17. 31-12-2	
3. 31-2-3	18. 31-12-3	
4. 31-5-1	19. 31-13-1	
5. 31-5-2	20. 31-13-2	
6. 31-5-3	21. 31-13-3	
7. 31-9-1	22. 31-16-1	
8 31-9-2	23. 31-16-2	
9. 31-9-3	24. 31-16-3	
10. 31-10-1	25.	
11. 31-10-2	26.	
12. 31-10-3	27.	
13. 31-11-1	28.	
14. 31-11-2	29.	
15. 31-11-3	30.	
SPECIAL INSTRUCTIONS: amalyze end	romageneaus area tile positive	
Relinquished by: Loslie Sell	Received by: Jennystar Ross	
Date: 1/31/00 Time: 35.7	Date: FEB 0 1 2000 ime:	

211/00 NAUY BILL RATE

5151 Brook Hollow Pkwy., Suite 250 Norcross, GA 30071 Phone: (770) 242-39033 Fax: (770) 242-3912

CHAIN OF CUSTODY FORM

BAT PROJECT CONTAC	BAT PROJECT CONTACT DOUGLAS J. MILTON			
BAT JOB NAME	Charleston Naval Shipyard	BAT JOB NO. 971001	TASK NO. 13.03	
ANALYSIS REQUESTE	D PLM - PCM -	AAS For Lead Content OTHER		
CHECK ONE: ROUTINE ROUTINE - FAX (HANDWRITTEN) RUSH - FAX (HANDWRITTEN) AS SOON AS POSSIBLE RUSH - FAX (HANDWRITTEN)				
SAN	IPLE ID	SAMPLE II)	
1. Exterior Pipe-32		16. B35-S1		
2. Exterior Pipe-34		17. B35-S2		
3. Exterior Pipe-36		18. B35-S3		
4. B31-S1		19.		
5. B31-S2		20.	· · · · · · · · · · · · · · · · · · ·	
6. B31-S3		21.		
7. B32-S1		22.		
8. B32-S2		23.		
9. B32-S3		24.		
10. B33-S1		25.		
11. B33-S2		26.		
12. B33-S3		27.	· · · ·	
13. B34-S1		233.		
14. B34-S2		29.		
15. B34-S3		30.		
SPECIAL INSTRUCTIONS: amalyze each homogeneous area till positive Relinquished by: Selle Received by: Jennystan Plass				
Relinquished by:	: Rell	Received by: Jonneystan	Ross	
Date: 1/33/00	Time: /357	Date: FFR 0 1 2000 Time:		
2/1/00	NAUY BILL A			

BAT Associates, Inc. environmental, health & safety services

5151 Brook Hollow Pkwy., Suite 250 Norcross, GA 30071

Phone: (770) 242-39032 Fax: (770) 242-3912

CHAIN OF CUSTODY FORM

BAT PROJECT CONTA	BAT PROJECT CONTACT DOUGLAS J. MILTON			
BAT JOB NAME	Charleston Naval Shipyard	BAT JOB NO. 971001	TASK NO. 13.03	
ANALYSIS REQUESTI	ANALYSIS REQUESTED PCM AAS For Lead Content OTHER			
CHECK ONE: ROUTINE ROUTINE - FAX (HANDWRITTEN) RUSH - FAX (HANDWRITTEN) AS SOON AS POSSIBLE RUSH - FAX (HANDWRITTEN)				
SAI	MPLE ID	SAMPLE ID		
1. 32-2-1		16. 32-7-1		
2. 32-2-2		17. 32-7-2		
3. 32-2-3		18. 32-7-3	-	
4. 32-3-1	-	19. 32-8-1		
5. 32-3-2		20. 32-8-2		
6. 32-3-3		21. 32-8-3		
7. 32-4-1		22. 32-11-1		
8 32-4-2		23. 32-11-2		
9. 32-4-3		24. 32-11-3		
10. 32-5-1		25.		
11. 32-5-2		26.		
12. 32-5-3		27.		
13. 32-6-1		28.		
14. 32-6-2		29.		
15. 32-6-3		30.		
SPECIAL INSTRUCTION	SPECIAL INSTRUCTIONS: analyse lab homogeneous area tier positive			
Relinquished by:	hie Bell	Received by: Jennestan		
Date: 1/31/00	Time: 1357	Date: Time:		
2/1/00 NAUY BILL RATE				

BAT Associates, Inc.
ENVIRONMENTAL, HEALTH & SAFETY SERVICES

5151 Brook Hollow Pkwy., Suite 250

Norcross, GA 30071 Phone: (770) 242-39034 Fax: (770) 242-3912

CHAIN OF CUSTODY FORM

BAT PROJECT CONTACT DOUGLAS J. MILT		MILTON		
BAT JOB NAME	Charleston Naval Shipy	ard BAT JOB NO.	971001	TASK NO. 13.03
ANALYSIS REQUES	TED ■ PLM □ PCN	1 □ AAS For Lead Cor	ntent □ OTHER_	
CHECK ONE:	ROUTINE ROUTINE - FAX (HAN RUSH - FAX (HANDW		SOON AS POSS SOON AS POSS	
S	AMPLE ID		SAMPLE ID	
1. 33-4-1		16.		
2. 33-4-2		17.		
3. 33-4-3		18.		_
4. 33-5-1		19.		-
5. 33-5-2		20.		
6. 33-5-3		21.	_	
7. 33-8-1		22.		
8 33-8-2		23.		
9. 33-8-3		24.		
10. 33-9-1		25.		_
11. 33-9-2		26.	_	
12. 33-9-3	_	27.	-	
13. 33-11-1		28.		-
14. 33-11-2		29.		
15. 33-11-3		30.		
SPECIAL INSTRUCT	IONS: Amaluso ear	h homasine	aus asea	tile sositue
Relinquished by:	ions: amalyzo ear	Received by:	Jennysta	, Ross
Date: 1/33/60	Time: /357		1 2000 Time:	

4/1/00 NAUY BILL rate

5151 Brook Hollow Pkwy., Suite 250 Norcross, GA 30071

Phone: (770) 242-39034 Fax: (770) 242-3912

CHAIN OF CUSTODY FORM

BAT PROJECT CONTACT DOUGLAS J. 1	MILTON
BAT JOB NAME Charleston Naval Shipy	ard BAT JOB NO. 971001 TASK NO. 13.03
ANALYSIS REQUESTED ■ PLM □ PCM	M □ AAS For Lead Content □ OTHER
CHECK ONE: ROUTINE - FAX (HAN RUSH - FAX (HANDW	DWRITTEN) AS SOON AS POSSIBLE RITTEN) AS SOON AS POSSIBLE
SAMPLE ID	SAMPEE ID
1. 34-3-1	16. 34-10-1
2. 34-3-2	17. 34-10-2
3. 34-3-3	18. 34-10-3
4. 34-4-1	19. 34-11-1
5. 34-4-2	20. 34-11-2
6. 34-4-3	21. 34-11-3
7. 34-5-1	22. 34-12-1
8 34-5-2	23. 34-12-2
9. 34-5-3	24. 34-12-3
10. 34-6-1	25. 34-19-1
11. 34-6-2	26. 34-19-2
12. 34-6-3	27. 34-19-3
13. 34-8-1	28.
14. 34-8-2	29.
15. 34-8-3	30.
SPECIAL INSTRUCTIONS: Omalyuse la	et homageneous area tie positie
Relinquished by: Lesher Sell	Received by: Jonneystan Ross
Date: 1/34/00 Time: /357	Date: FFB 0.1 2000 Time:
41/00 NAUY BIL	L RATE

BAT Associates, Inc. ENVIRONMENTAL, HEALTH & SAFETY SERVICES 5151 Brook Hollow Pkwy., Suite 250

Norcross, GA 30071 Phone: (770) 242-39034 Fax: (770) 242-3912

CHAIN OF CUSTODY FORM

BAT PROJECT CONTAC	CT DOUGLAS J. MIL	TON				
BAT JOB NAME	Charleston Naval Shipyard	BAT JOB NO. 971001	TASK NO. 13.03			
ANALYSIS REQUESTED PLM PCM AAS For Lead Content OTHER_						
CHECK ONE:	■ ROUTINE - FAX (HANDWRITTEN) AS SOON AS POSSIBLE					
SAM	IPLE ID	SAMPLE ID				
1. 36-4-1		16.				
2. 36-4-2	·	17.				
3. 36-4-3		18.	_			
4. 36-5-1		19.				
5. 36-5-2		20.	_			
6. 36-5-3	·	21.				
7. 36-15-1		22.				
8 36-15-2		23.				
9. 36-15-3		24.				
10. 36-16-1		25.				
11.36-16-2		26.				
12.36-16-3		27.	_			
13.		28.				
14.		29.				
15.		30.	_			
SPECIAL INSTRUCTIONS: Comalyar each homogeneous oneg tile positive						
Relinquished by:	je Zell	Received by: Jennziten Prose				
Date: 1/33/00	Time: /357	Date: FEB 0 1 2000 Time:				
2/1/00 NAUY BILL rate						

NAUY BILL rate

OF THE OF MON TIME EVY 110 AND 1700

BAT

BAT Associates, Inc.
ENVIRONMENTAL, HEALTH & SAFETY SERVICES

5151 Brook Hollow Pkwy., Suite 250 Norcross, GA 30071 Phone: (770) 242-3908 Fax: (770) 242-3912

CHAIN OF CUSTODY FORM

BAT PROJECT CONTACT DOUGLAS J. MILTON						
BAT JOB NAME Charleston Naval Shipya	ard BAT JOB NO. 971001 TASK NO. 13.03					
ANALYSIS REQUESTED PLM PCM AAS For Lead Content OTHER						
CHECK ONE: ROUTINE ROUTINE ROUTINE - FAX (HANDWI						
SAMPLE D.	SAMPLETD					
1. 76-1-1QC	16. 34-4-190					
2. 76-4-1QC	17. 34-610C					
3. 76-8-10C	18. 34-5-196					
4. 76-9-1QC	19. 36-4-1QC					
5. 76-12-1QC	20. BAT 199-2-19C					
6. 76-15-1QC	21. RAT199-1-19C					
7.76-16-10C	22.BATM9-4-1GC					
8. 76-21-1QC	23. BAT199-5-10C					
9.76-23-1QC	24. BAT199-7-1QC					
10.31-5-1QC	25. BAT199-10-19C					
11.31-10-190	26. BAT199-17-19C					
12. 32-2-166	27.					
13. 32-3-190	28.					
14. 33-5-19L	29.					
15. 34-3-196	30.					
SPECIAL INSTRUCTIONS: AND TO SEE TO S						
Relinquished by: Loshie Bell	Received by:					
Date: 12/29/99 Time:	Date: 2/1/0P Time: 2.32					

TEL: (770) 908-7200

FAX: (770) 908-7219

PLM ANALYSIS ASBESTOS SUMMARY *

CLIENT NAME:

BAT ASSOCIATES

PROJECT NO:

00003.000.000

PROJECT NAME:

ENVIRONMENTAL

MANAGEMENT N

G. S. S.

CHARLESTON NSY / 971001-13.03

LAB JOB NO:

B0018

DATE RCVD:

2/1/00

	Sample Lab ID	SAMPLE FIELD ID	LAYER NUMBER	APPEARANCE	LOCATION / DESCRIPTION	% asbestos (comments)
17	1032	34-4-1QC		BLUE HARD RESILIENT TO GRANULAR WITH BLACK MASTIC		4%CHR (6% CHRYSOTILE II BLACK MASTIC)
18	1033-1	34-6-1QC	1 (of 2)	RED HARD RESILIENT TO GRANULAR		•
19 .	1033-2	34-6-1QC	2 (of 2)	BLACK MASTIC WITH FIBERS		7%CHR
20	1034	34-5-1QC		YELLOW HARD RESILIENT TO GRANULAR WITH BLACK MASTIC	:	5%CHR (7% CHRYSOTILE IN BLACK MASTIC)
21	1035	36-4-1QC		GRAY HARD RESILIENT TO GRANULAR WITH BLACK MASTIC		7%CHR (4% CHRYSOTILE IN BLACK MASTIC)
22	1036	BAT199-2-1QC		PINK HARD RESILIENT TO GRANULAR WITH YELLOW GUMMY MASTIC		•
23	1037	BAT199-1-1QC		BLACK HARD RESILIENT TO GRANULAR WITH FIBERS AND BLA MASTIC	ck	5%CHR (3% CHRYSOTILE II BLACK MASTIC)
24	1038	BAT199-4-1QC		GRAY SEMI-HARD RESILIENT WITH BROWN MASTIC		•
25	1039	BAT199-5-1QC		GRAY SEMI-HARD RESILIENT		-
26	1040	BAT199-7-1QC		GRAY SOFT FIBROUS TO GRANULAR TO POWDERY WITH PAIN	ŀΤ	•
27	1041	BAT199-10-1QC		BLACK SOFT BITUMINOUS WITH FIBERS AND ALUMINUM FOIL		5%CHR
28	1042	BAT199-17-1QC		GRAY SOFT RESILIENT WITH ALUMINUM FOIL, CANVAS, AND YELLOW FIBERS		-
29	1043-2	1777-3-1QC	2 (of 2)	BLACK SOFT BITUMINOUS WITH FIBERS		3%CHR (SAMPLE NOT ON CHAIN-OF-CUSTODY)
30	1043	1777-1-1QC		NOT RECEIVED		(NOT ANALYZED)
31	1043-1	1777-3-1QC	l (of 2)	GREEN HARD RESILIENT TO GRANULAR WITH FIBERS		(SAMPLE NOT ON CHAIN-OF CUSTODY)

^{*} If box "QC" is not checked, these results are provided before full QC is completed and therefore could be changed.

QC

"-" = NO ASBESTOS DETECTED